Submit One Copy To Appropriate District	State of New Me	exico	Form C-103
	Energy, Minerals and Natural Resources		Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-045-28069	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION	5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Gallegos Canyon Unit
PROPOSALS.)			8. Well Number 514
1. Type of Well: Oil Well Gas Well Other			WOL 2 1 COS S 100 COS S 100 COS S 100 COS S
2. Name of Operator BP America Production Company			9. OGRID Number 000778
3. Address of Operator			10. Pool name or Wildcat
1199 Main Ave, Durango, CO 81301			Basin Fruitland Coal
4. Well Location			
Unit Letter O: 880 feet from the	ie South line and 2415 feet	from the East line	
Section 34 Township 29N Range 12W NMPM County San Juan			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
5304'			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR			
PULL OR ALTER CASING MULT	IPLE COMPL	CASING/CEMEN	II JOB
OTHER:		□ Location is a location in location.	ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER,			
SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE			
MARKER S SURFACE			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other			
production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the			
terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be			
removed.)			
All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location,			
except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule an inspection. All work was completed on 3/26/2019			
SIGNATURE Sabre J. Berbe	TITLE Com	pliance Specialist	DATE _January 28, 2020
TYPE OR PRINT NAME Sabre J. Beebe_E-			
F- Ct -t II- O I		x.com_ PHONE. 3	7/0-//9-9398
Mhn Lill	Man	Denistra Oil o	Contraporter 21 FGA
APPROVED BY:	TITLE	Deputy Oil 8	Gas inspector DATE 26-765-2020
APPROVED BY: APPROVED BY: Conditions of Approval (if any):	2	DIS	
V	1. 4		NMOCD
		-	ED 4 0 2020
		r	EB 1 0 2020

DISTRICT III

BP L48 San Juan



Form Information

Form Name: Submitter Name: Submission Date: Server Receive Date: Reference Number:

Compliance Follow Up Form Julian Martinez (julianmartinez) Jan 23, 2020 1:16:22 PM MST Jan 23, 2020 1:16:29 PM MST 20200123-18130631407 17 Rd 5500, Farmington, NM 87

Location: 17 Rd 5500, Farmington, NM 87401, USA Jan 23, 2020 1:09:24 PM MST [<u>View Map</u>]

Information

Name Date

Optional - Type Part of the Run Number or Lateral to Filter for Next Question

Location Name (Other)
Location API (Other)

Select State
Work type
Action Complete

Photo of first corrective action completed

julianmartinez Jan 23, 2020 GCU 514

Gallegos Canyon Unit 514 3004528069 New Mexico


Plug & Abandonment Work Equipment Stripping



Completed work description Corrective Action 1 Photo of second corrective action completed Equipment strip off complete - photo to the North




Completed work description of corrective action 2 Photo of third corrective action completed





Completed work description of corrective action 3 Photo of fourth corrective action completed





Completed work description

Completed work description of corrective action 4

Completed work description

Summary of all work completed

Equipment strip off complete - photo to the West Plug and abandonment - Equipment strip off complete

Plug and abandonment - Equipment strip off complete

Plug and abandonment - Equipment strip off complete