submitted in lieu of Form 3160-5

UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU	OF	LAND	MANAGEMENT	1	1	1	

Sundry Notices and Reports on Wells		
		, , , , , , , , , , , , , , , , , , ,
	5.	Lease Number
N.G.A		NMNM01772A
. Type of Well 970 Farmington, NM	6.	
GAS		Tribe Name
	7.	Unit Agreement Name
. Name of Operator	, .	Unit Agreement Name
BURLINGTON		
RESOURCES OIL & GAS COMPANY		
	8.	· · · · · · · · · · · · · · · · · · ·
. Address & Phone No. of Operator	_	Neudecker #7M
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	
. Location of Well, Footage, Sec., T, R, M	10	30-045-31664 Field and Pool
1505'FNL, 1845'FWL, Sec.13, T-29-N, R-10-W, NMPM	10.	Otero Chacra/Blanco
1505 The, 1015 The, 500.15, T as M, M 10 M, MHM		Mesaverde/Basin Dako
	11.	County and State
		San Juan Co, NM
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,	OTHER	DATA
Type of Submission Type of Action		
Notice of Intent Abandonment Change	of Pla	ans
Recompletion New Co		
X Subsequent Report Plugging Back Non-Ro Casing Repair Water	Shut o	Fracturing Ff
casing Repair water		
Final Abandonment Altering Casing Conver	sion to	
	sion to	
Final Abandonment Altering Casing Conver X Other - Spud, casing, & ce	sion to	
Final Abandonment Altering Casing Conver X Other - Spud, casing, & ce	sion to	
Final Abandonment Altering Casing Conver X Other - Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'.	circ h	o Injection ole clean.
Final Abandonment Altering Casing Conver X Other - Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg,	Circ ho	ole clean.
Final Abandonment Altering Casing Conver X Other - Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash	Circ ho	ole clean. 139'. ft.).
Final Abandonment Altering Casing Conver X Other - Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg,	Circ ho	ole clean. 139'. ft.).
Final Abandonment Altering Casing Conver X Other - Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash	Circ ho	ole clean. 139'. ft.).
Final Abandonment Altering Casing Conver X Other - Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash	Circ ho	ole clean. 139'. ft.).
Final Abandonment Altering Casing Conver X Other - Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash	Circ ho	ole clean. 139'. ft.).
Final Abandonment Altering Casing Conver X Other - Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash	Circ ho	ole clean. 139'. ft.).
Final AbandonmentAltering CasingConverX_Other - Spud, casing, & cess. 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho	ole clean. 139' ft.). eased.
Final AbandonmentAltering CasingConverX_Other - Spud, casing, & cess. 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho	ole clean. 139' ft.). eased.
Final AbandonmentAltering CasingConverX_Other - Spud, casing, & cess. 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho	ole clean. 139' ft.). eased.
Final AbandonmentAltering CasingConverX_Other - Spud, casing, & cess. 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho	ole clean. 139' ft.). eased.
Final AbandonmentAltering CasingConverX_Other - Spud, casing, & cess. 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho	ole clean. 139' ft.). eased.
Final AbandonmentAltering CasingConverX_Other - Spud, casing, & cess. 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho	ole clean. 139' ft.). eased.
Final AbandonmentAltering CasingConverX_Other - Spud, casing, & cess. 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho	ole clean. 139' ft.). eased.
Final AbandonmentAltering CasingConverX_Other - Spud, casing, & cess. 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho	ole clean. 139' ft.). eased.
Final AbandonmentAltering CasingConverX_Other - Spud, casing, & cess. 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho	ole clean. 139' ft.). eased.
Final AbandonmentAltering CasingConverX_Other - Spud, casing, & cess. 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho	ole clean. 139' ft.). eased.
Final Abandonment	Circ ho	ole clean. 139' ft.). eased.
Altering Casing Conver X Other - Spud, casing, & ce 2. Conver Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F. APD ROW Related	Circ ho set @ (81 cu hig rel	ole clean. 139' ft.). eased.
Altering Casing Conver X Other - Spud, casing, & ce 2. Conver Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F. APD ROW Related	Circ ho set @ (81 cu hig rel	ole clean. 139' ft.). eased.
	Circ ho set @ (81 cu hig rel	ole clean. 139' ft.). eased.
Altering Casing Conver X Other - Spud, casing, & ce 2. Conver Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F. APD ROW Related	Circ ho set @ (81 cu hig rel	JUL 2003 GCEPTED=FOR RECORL
Final Abandonment X Other - Spud, casing Conver X Other - Spud, casing, & ce 3. Describe Proposed or Completed Operations 7/3/03 MIRU. Spud well @ 8:15 am 7/3/03. Drill to 140'. TOOH. TIH w/4 jts 9-5/8" 32.3# H-40 ST&C csg, Cmtd w/50 sxs Type III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F APD ROW Related APD ROW Related Title Regulatory Supervious space for Federal or State Office use) PPROVED BY Title III Portland III Portland w/20% flyash Circ 2 bbls cmt to surface. WOC. NU WH. RD. F	Circ ho set @ (81 cu hig rel	JUL 2003
Final Abandonment	Circ he set @ (81 cu Rig rel	JUL 2003 JUL 2003 JUL 1 1 2003