District I 1625 N. French Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For drilling and production facilities, submit to

Form C-144


June 1, 2004

appropriate NMOCD District Office. For downstream facilities, submit to Santa Fe office

## Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes X No Type of action: Registration of a pit or below-grade tank Closure of a pit or below-grade tank X Operator: Koch Exploration Company, LLC Telephone: (505) 334-9111 \_\_\_e-mail address: \_clark23j@kochind.com or johnso4d@kochind.com\_ Address: PO Box 489, Aztec, NM 87410 Facility or well name: \_\_Seymour 719S\_\_\_\_\_\_API #: \_30-045-32529\_\_\_\_\_U/L or Qtr/Qtr\_\_C\_\_Sec\_14\_\_T\_31N\_\_R\_9W\_\_\_ County: San Juan Latitude 36.54.1850 Longitude 107.45.31489 NAD: 1927 1983 Surface Owner Federal X State Private Indian Below-grade tank Pit Volume: \_\_\_\_\_bbl Type of fluid: \_\_\_\_\_\_ Type: Drilling Production Disposal Workover X Emergency Construction material: Lined X Unlined Double-walled, with leak detection? Yes If not, explain why? Pit Volume (20 points) Less than 50 feet Depth to ground water (vertical distance from bottom of pit to seasonal high (10 points) 50 feet or more, but less than 100 feet water elevation of ground water.) X 100 feet or more ( 0 points) (20 points) Wellhead protection area: (Less than 200 feet from a private domestic X No ( 0 points) 0 points water source, or less than 1000 feet from all other water sources.) Less than 200 feet (20 points) Distance to surface water: (horizontal distance to all wetlands, playas, 200 feet or more, but less than 1000 feet (10 points) irrigation canals, ditches, and perennial and ephemeral watercourses.) ( 0 points) 0 points X 1000 feet or more 0 points Ranking Score (Total Points) If this is a pit closure: (1) attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if . (3) Attach a general description of remedial action taken including your are burying in place) onsite \( \subseteq \) offsite \( \subseteq \) If offsite, name of facility\_ remediation start date and end date. (4) Groundwater encountered: No 🛛 Yes 🗖 If yes, show depth below ground surface \_\_\_\_\_\_ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations. Additional Comments: CLOSURE I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit outletow-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit X or an (attached) alternative Of Date: 06/29/06 Printed Name/Title\_John Clark, District Superintendent\_ Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with ny other federal, state, or local laws and/or regulations. Approval:
Printed Name/Title Branston Tang Approval: DEPUTY OIL & GAS INSPECTOR, DIST. (3) \_\_\_\_\_\_0 3 **2006** 

## KOCH EXPLORATION COMPANY LLC Seymour 719S S14, T31N, R9W 750' FNL & 1660' FWL - ELEVATION 6513'



Seymour 719S

S14, T31N, R09W, 750' FNL & 1660' FWL San Juan Co., New Mexico API No. 30-045-32529 Lease SF078505

Upon completion of cleanout/workover remaining liquids were removed from pit by truck to an approved disposal facility.

Prior to closing the pit, liner was cut off at mud level. The excess liner was hauled to a licensed disposal.

May 19 through May 24, 2006 the remaining waste in pit was encapsulated. This was accomplished by covering the remaining waste and liner with earthen materials. Surface area where pit was located was contoured according to BLM requirements, and will be reseeded with recommended BLM seed mixture, at a later date this year.