4			5. Lease	Contain Water Co. C.
UNITED STATES			NMNM-03733	
DEPARTMENT OF THE INTERIOR				
BUREAU OF LAND MANAGEMENT			6. If Indian, Allottee or Tribe Name 7. Unit Agreement Name ECELVED 46	
BUREAU OF LAND MANAGEMENT			6. If Indian, Allotte	e or Tribe Name
SUNDRY NOTICES AND REPORTS ON WELLS			7. Unit Agreement	Name Con to 10: 11
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals)				- 17 14 14 14 14 14 14 14 14 14 14 14 14 14
1. Oil Well [] Gas Well [] Other []			8. Well Name and I	No. 1777
GAS WELL			BREECH 307 Wy	
2. Name of Operator:			9. API Well No. 30-039-08157-00C1	
Caulkins Oil Company 3. Address of Operator: (505) 224, 4222			10. Field and Pool, Exploratory Area	
(303) 334-4323			DAKOTA, MESA VERDE, CHACRA	
1409 W. Aztec Blvd. Ste B7, Aztec, NM 87410 4. Location of Well (Footage, Sec., Twp., Rge.)			11. Country or Parish, State	
790' F/S 1140' F/W SEC. 13-26N-7W			Rio Arriba Co., New Mexico	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION TYPE OF ACTION				
[] Notice of Intent		[] Abandonment	<u> </u>	
[X] Subsequent Report [] Final Abandonment Notice		[]Recompletion		[] New Construction
		[] Plugging Back [] Casing Repair		[] Non-Routine Fracturing [] Water Shut-Off
		Casing Repair Altering Casing		[] Conversion to Injection
		[X] Other <u>Clean Out</u>		Dispose Water
17. Describe Proposed or Completed Operations:				
5-17-07 Rigged up.				
То		d up. d up on 2 3/8" tubing, tubing stuck.		
5-21-07	•	ee-point, tubing stuck on bottom joint.		
3-21-07	Ran free-point, tubing stuck on bottom joint. Cut tubing off leaving 56' of tubing on bottom. Top of fish at 6735'. MAY 2007			
Cut tubing off leaving 56' of tubing on bottom. Top of fish at 6735'. MAY 2007				
T. O. H. with tubing.				
T. I. H. with wash-over pipe and over-shot.				
To Picked up on 2 3/8" tubing, tubing stuck. 5-21-07 Ran free-point, tubing stuck on bottom joint. Cut tubing off leaving 56' of tubing on bottom. Top of fish at 6735'. T. O. H. with tubing. T. I. H. with wash-over pipe and over-shot. Unable to get past bad spot in casing at 4716' with wash-over pipe. T. O. H. laying down fishing tools.				
T. O. H. laying down fishing tools.				
T. I. H. with 2 3/8" production tubing.				
Landed tubing on doughnut at 6716' with Model R-3 packer set at 3394' with reverse flow check valve immediately above packer.				
This isolates Dakota – Mesa Verde below packer with Chacra flowing through check valve above packer.				
Rigged down and moved.				
NOTE: The format is issued in lieu of U.S. BLM Form 3160-5				
18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT				
SIGNED: About 7 Verque TITLE: Superintendent DATE: May 22, 2007				
	DBERT L. VERQUER	TITES. Supermender	1714. 1714.	
APPROVED B	V·	TITLE:	DATE:	ACCEPTED FOR RECORD
	OF APPROVAL, IF ANY	111LC	DATE	0.1.7.00
				MAY 2 5 2007
11				