, <del></del>				PN
Submit 3 Copies To Appropriate District	Appropriate District State of New Mexico			Form C-103
Office District I	Energy, Minerals and Natu		Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-045-23573  5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE	FEE X
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		0 10 11 12 13 14		
SUNDRY NOTICI (DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICA"	ES AND REPORTS ON WELLS	19 A	7. Lease Name or	Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICA"	LS TO DRILL OR TO DEEPEN OR PL FION FOR PERMIT" (FORM C-101) <b>I</b>	SUCH DEC 2002	HI HI	utchin LS
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)  1. Type of Well:	(L	OR CONS. DI	20	
Oil Well Gas Well	Other	OIST 3	v. 23	
2. Name of Operator	Au. 11	E.	8. Well No.	
BP America Production Company  3. Address of Operator	Attn: Mary Corley	F2071792	9. Pool name or V	
P.O. Box 3092 Houston, TX 77253		20C0C1C39		Pictured Cliffs
4. Well Location				
Unit Letter G 1	500 feet from the North 1	ine and <b>1540</b> f	eet from the <b>Eas</b>	st line
	ownship 31N Range 10. Elevation (Show whether D		MPM San Juan	County
	10. Elevation (Snow whether D			
11. Check Ap	propriate Box to Indicate N	ature of Notice,	Report or Other I	Data
NOTICE OF INT			SEQUENT REI	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	к Ц	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
•	MULTIPLE   COMPLETION	CASING TEST AND CEMENT JOB		
OTHER:		OTHER:		
	operations (Clearly state all ne		rive pertipent dates	including estimated date
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
11/27/2002 Check anchors. MIRU workover rig. ND WH. NU BOPs. TIH w/CIBP & set @ 2550'. Loaded hole &				
Pressure tested to 500#. Test OK. Spot 500' cement plug (16.5 cu ft) above CIBP from 2050'-2550'. TOH. RU WL unit.				
TIH & shoot SQZ holes at 1275'. TIH w/CMT retainer & set @ 1250'. TIH & sting into retainer & pump 15.5 BBLS CMT. Sting out pump 1.5 BBLS CMT. PU & CMT from 290' to surface. ND BOPs. Cut off wellhead and install P&A marker.				
RDMOWR. Rig released 12/03/2002				
Surface location turned over to environmental group for surface restoration.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE MALE AND THE ST Regulatory Analyst DATE 19/00/2002				
SIGNATURE /////USY / SULLY TITLE Sr. Regulatory Analyst DATE 12/09/2002				
Type or print name Mary Corley (This space for State use),			Telephone No. 28	1-366-4491
4/ 1-1/	nepi	ITY OIL & GAS INSP	ECTOR. DIST. 🙉	OCT OA
APPPROVED BY H. Villanueva TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 35 DATE 24 2003  Conditions of approval, if any:				
10-24-03				