District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr , Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## **Release Notification and Corrective Action**

			(	OPERATOR ☐ Initial Report ☐ Final Report						Final Report				
Name of Company XTO Energy Inc.						Contact Kim Champlin								
Address #382 County Road 3100						Telephone No. (505) 333-3100								
Aztec, NM : Facility Nan		FC #1 (ADI		Facility Type Gas Well										
Surface Own	ner Feder	·al	Lease No. NMNM09867A											
				LOCA	TION	OF REI	LEASE							
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/W	est Line	County				
E	05	30N	13W	2380	North		725 West			San Juan				
Latitude 36.84294						Longitude	108.23469	·						
NATURE OF RELEASE  Type of Release Produced Water Volume of Release Approx 220 Volume Recovered Approx 210 bbl												v 210 bbl		
Type of Release Froduced water							bbl				Volume Recovered Approx 210 bbi			
Source of Release Vertical Separator										nd Hour of Discovery				
Was Immediate Notice Given?						07/29/08, time unknown 0 If YES, To Whom?				07/29/08 at 8:00 am				
Yes ☐ No ☐ Not Required							Brandon Powell							
By Whom? Kim Champlin						Date and Hour 07/30/08 10:00 am RCUD AIG 12 'OB If YES, Volume Impacting the Watercourse. DIL CONS. DIV.								
Was a Watercourse Reached? ☐ Yes ☒ No							36.7.7.4							
							N/A DIST. 3							
If a Watercourse was Impacted, Describe Fully.* N/A														
Describe Cause of Problem and Remedial Action Taken.* An XTO employee arrived on location and discovered the pit cellar filling with produced water. The well was shut in to determine the problem. During the investigation it was discovered that on 7/28/08 pump and tubing repairs had been made and well was put back online at about 5:30pm. The mechanical dump on the vertical separator had hung open at some point after the repairs, venting the casing gas to the pit tank. This caused the casing to unload water and filled the pit tank, the pit cellar and was accumulating in the berm around the production equipment. A water truck was dispatched immediately and approximately 210 barrels of standing water was recovered. All produced water was contained within the berms and no water left location. All repairs were made and the well was put back online.														
Describe Area Affected and Cleanup Action Taken.* The well was shut in and a vac truck was dispatched immediately. Repairs were made and														
the well was observed for verification. All standing water was recovered.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.														
Signature:	Kun	Cha		OIL CONSERVATION DIVISION										
Printed Name	: Kim Ch		Approved by District Supervisor: Bud For: Charlie Perring											
Title: Environmental Representative						Approval Date: 8/12/08 Expiration Date:								
E-mail Address: Kim_Champlin@xtoenergy.com  Date: 08/11/08 Phone: 505-333-3100						Conditions of Approval:				d 🔲				
	11/08		L					1						
Attach Addit	Attach Additional Sheets If Necessary  Incident # 1 Pal 0928253339													