

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Energen Resources, Inc.	Contact: Ed Hasely	
Address: 2010 Afton Place, Farmington, NM 87401	Telephone No: 505-324-4131	
Facility Name: Rowley D #2; API No. 3004506214	Facility Type: Oil/Gas Well Site	
Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF-077951A

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	27	27N	10W	790	South	790	West	San Juan

Latitude 36.5411

Longitude -107.88857

RCVD APR 24 '09
OIL CONS. DIV.

NATURE OF RELEASE

Type of Release: Compressor Fire	Volume of Release: 75 MCF - Natural Gas	Volume Recovered: 0
Source of Release: Compressor	Date and Hour of Occurrence: 3/25/08 12:30 pm	Date and Hour of Discovery: 3/26/08 10:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom: Brandon Powell - NMOCD (message) Cliff Ollom - BLM (message)	
By Whom? Ed Hasely	Date and Hour: 3/26/08 1:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	



If a Watercourse was Impacted, Describe Fully.* NA

Describe Cause of Problem and Remedial Action Taken.*

A compressor fire was discovered on the subject location at approximately 10:45 am on 3/26/08. The well was shut-in and the fire was extinguished. Records show that the unit went down around 2:30 pm on 3/25/08, so it is estimated that the fire may have burned for 20 hours. The unit was severely damaged making the exact cause of the fire impossible to determine, but investigations point to the possibility of severe vibration problems, which led to a piping failure.

Describe Area Affected and Cleanup Action Taken.* Fire was confined to the compressor skid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ed Hasely	Approved by District Supervisor:  For: Charlie Perrin	
Title: Sr. Environmental Engineer	Approval Date: 4-24-09	Expiration Date:
E-mail Address: ed.hasely@energen.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/01/09 Phone: 505-324-4131 / 505-330-3584(cell)		

* Attach Additional Sheets If Necessary

Incident # N RMD 0924537331