

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Energen Resources, Inc.	Contact: Ed Hasely	
Address: 2010 Afton Place, Farmington, NM 87401	Telephone No: 505-324-4131	
Facility Name: Santa Rosa 4 #2; API No. 3004528159	Facility Type: Oil/Gas Well Site	
Surface Owner: Fee	Mineral Owner: Fee	Lease No. Fee

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	4	29N	9W	1290	South	1870	West	San Juan

Latitude 36.75018

Longitude -107.78672

### NATURE OF RELEASE

Type of Release: Pumping Unit Engine Fire	Volume of Release: <1 MCF - Natural Gas	Volume Recovered: 0
Source of Release: Pumping Unit Engine	Date and Hour of Occurrence: 2/5/09	Date and Hour of Discovery: 2/5/09 12 noon
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom: Brandon Powell - NMOCD	
By Whom? Ed Hasely	Date and Hour: 2/6/09 7:20 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

RCVD FEB 11 '09

If a Watercourse was Impacted, Describe Fully.\* NA



OIL CONSV. DIV.  
DIST. 3

#### Describe Cause of Problem and Remedial Action Taken.\*

A pumping unit engine fire was discovered on the subject location at approximately 12 noon on 2/5/09. The small fire had gone out prior to discovery. Investigations point to the possibility of the exhaust hose igniting insulation on the fuel gas line, which then damaged a regulator allowing a small amount of fuel gas to be released.

Describe Area Affected and Cleanup Action Taken.\* Fire was confined to the area near the pumping unit.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ed Hasely	Approved by District Supervisor:  For: Charlie Perrin	
Title: Sr. Environmental Engineer	Approval Date: 2/11/09	Expiration Date:
E-mail Address: ed.hasely@energen.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/9/09 Phone: 505-324-4131 / 505-330-3584(cell)		

\* Attach Additional Sheets If Necessary

nBP0918937425