

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-045-26845

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Enterprise Field Services LLC	Contact: Don Fernald
Address: 614 Reilly Avenue / Farmington, NM	Telephone No. 505-599-2124
Facility Name: Hartman Com #4 MV	Facility Type: Gas Production Location / Meter
Surface Owner	Mineral Owner
Lease No.	

LOCATION OF RELEASE

Unit Letter	Section 26	Township 30 North	Range 11 West	Feet from	North/South Line	Feet from the	East/West Line	County
-------------	---------------	----------------------	------------------	-----------	------------------	---------------	----------------	--------

Latitude 36.78657 North Longitude 107.95481 West

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 579.6 mcf	Volume Recovered: None
Source of Release: Damaged 2" meter line	Date and Hour of Occurrence: Approximately 8:00 AM 1/14/07	Date and Hour of Discovery: 1:15 PM 1/15/07
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell / NMOCD - Aztec / Phone Call	
By Whom? Don Fernald	Date and Hour: 1/16/07 - 1:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

It appears as though a vandal/thief hooked a chain or rope around the meter house antenna (attached to meter house) and pulled it with a vehicle in order to steal the solar panel. The meter house collapsed and damaged a two-inch gas line. The event was reported to the local authorities.

Describe Area Affected and Cleanup Action Taken.*

Once the release was discovered, the piping was isolated and blown down in order to complete repairs.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Don Fernald	Approved by District Supervisor: 	For: Charlie Perrin
Title: Environmental Scientist	Approval Date: 1-23-07	Expiration Date:
E-mail Address: dferald@eprod.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/19/07	Phone: 505-599-2124	

* Attach Additional Sheets If Necessary

1111K 0934534268