<u>District I</u>
1625 N. French Dr., Hobbs, NM 88240
<u>District II</u>
1301 W. Grand Avenue. Artesia, NM 88210
<u>District III</u>
1000 Rio Brazos Road, Aztec, NM 87410
<u>District IV</u>

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Form C-141 Revised June 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Attached

1220 S. St Francis Dr., Santa Fe. NM 87505	Sa	ınta Fe.	NM 87505	5		side of form	
Release 30 045 20448	se Notifica		nd Correct	tive Action	☐ Initial Report	✓ Final Report	
Name of Company Burlington Resources							
			86				
Tion Box (20) Turningcon Tim 67 (77)							
Facility Name HUERFANO UNIT 188			Facility Type Gas Well				
Surface Owner Fed Mineral Owner			Fed		Lease No. NMSF-079231		
	LOCAT	TION O	F RELEA	SE			
Unit Letter Section Township Range Feet from the	North/Sou	th Line	Feet from the	East/West Line	<u> </u>	,	
M 06 025N 009W 800	Sou	ıth	900	West	San Jua	in	
	NATU	J RE O I	FRELEAS	SE			
Type of Release Condensate (18 bbls) and Produced	water (6 bbl	Volume o	f Release	24 BBLS.	Volume Recovered	0 BBLS	
Source of Release Production Storage Tank			Hour of Occure		Date and Hour of Discovery		
Was Immediate Notice Given?			1/31/2005 1/31/2005 If YES, To Whom? Denny Foust				
By Whom? Gregg Wurtz			Date and Hour				
Was a Watergourea Deschad?			If YES, Volume Impacting the Watercourse.				
Yes ✓ No If a Watercourse was Impacted, Describe Fully.*							
Describe Cause of Problem and Remedial Action Taken * A small pin hole leak in the base of storage tank along a	weld contact s	seam. The	e tank was rem	oved and repla	ced with a new tank	PES 2005 RECORDS DIST. 8	
Describe Area Affected and Cleanup Action Taken.* An area 3X3 feet soil stain adjacent to tank leak. The so The impacted soil was landfarmed on the incident location discovered at 6 - 8 feet in depth. A minor area at bottom extent of impacted soil overburden was removed above t	on and the adj n of excavation the sandstone.	acent Huron 6 feet x Clean fill	efano #189. T 6 feet had visa l soil was back	The excavation able staining on afilled into exca	stopped at sandstone sandstone. The reavation and the locat	that was maining lateral ion was	
I hereby certify that the information given above is true and or regulations all operators are required to report and/or file cert health or the environment. The acceptance of a C-141 report operations have failed to adequately investigate and remediate cenvironment. In addition, NMOCD acceptance of a C-141 state, or local laws and/or regulations.	tain release no ort by the NM contamination	tifications a IOCD mark that pose a	and perform conced as "Final Re a threat to grou	rrective actions for port" does not re and water, surface	or releases which may elieve the operator of le water, human health	endanger public iability should their or the	
Signature Signature Signature Signature Signature Wurtz Title. Environmental Representative	Approved by		19	SERVATION Cha	tour	eniu	

E-mail Address lhasely@br-inc. com or gwurtz@br-inc.com

Phone: (505) 326-9841or 9537

Conditions of Approval: