

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039 24259

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Mallon Oil Company	Contact <input type="checkbox"/> Doran Newlin
Address P.O. Box 2797 Durango, Co. 81302	Telephone No. <input type="checkbox"/> 907-382-9100
Facility Jicarilla 464 # 6	Facility Type Well Site

Surface Owner Jicarilla Apache Res.	Mineral Owner Mallon Oil Co.	Lease No. <input type="checkbox"/> Jic 464 # 6
--	---------------------------------	--

LOCATION OF RELEASE

Unit Letter	Section 12	Township T 30 N	Range R3W	Feet from the 100yd. from well site	North/South Line	Feet from the	East/West Line	County Rio Arriba <input type="checkbox"/>
-------------	---------------	--------------------	--------------	---	------------------	---------------	----------------	---

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30.0 bbls. Est.	Volume Recovered 25 bbls
Source of Release UNDERGROUND FLOW LINE SPLIT	Date and Hour of Occurrence 9-17-03 @ TIME ?	Date and Hour of Discovery 9-17-03 @ 8:00 AM
Was Immediate Notice Given? YES	If YES, To Whom? Doran Newlin, Jic. Epa Dixon Sanduval, Denny with OCD	
By Whom? Gary Stripling	Date and Hour <input type="checkbox"/> 9-17-03 @ 10:30 am	
Was a Watercourse Reached? No	If YES, Volume Impacting the Watercourse. DNA	

If a Watercourse was Impacted, Describe Fully.*
DNA

Describe Cause of Problem and Remedial Action Taken.* Gas line from the Jic. 464 # 6 split underground causing a gas and water leak . Was discovered by Orson Harrison our pumper. Called in water truck with Dawn Trucking and picked up 25bbls and hauled to our water disposal site. Sierra Construction moved onto location repaired line.

Describe Area Affected and Cleanup Action Taken.* The leak was located 30' radius 100 yds. South of well site, the soil was wet from fresh Water that was produced from the well. Fresh dirt was laid in place of wet. Hole was back field.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remedial contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gary Stripling</i>	OIL CONSERVATION DIVISION	
Printed Name: Gary Stripling	Approved by <input type="checkbox"/> District Supervisor: <i>Denny Reut</i> <i>Frank Chavez</i>	
Title: Plant Foreman	Approval Date: <i>9/30/03</i>	Expiration Date:
Date: 9-17-03	Phone: 486 - 2136	Conditions of Approval:
		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

11 DGF0326041805