

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company	BP America Production Company	Contact	Kelly Hart
Address	200 Energy Court, Farmington, NM 87401	Telephone No.	505-326-9200
Facility Name	Sammons CDP @ Sammons GC B 001A	Facility Type	Compressor

Surface Owner	Federal	Mineral Owner	Fee	Lease No.	N/A
---------------	---------	---------------	-----	-----------	-----

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	07	29N	09W	230'	South	790'	West	San Juan

Latitude 36° 43' 59.412" Longitude 107° 49' 28.704"

30-045-25021

**NATURE OF RELEASE**

Type of Release	Fire	Volume of Release	N/A	Volume Recovered	N/A
Source of Release	Engine Starter	Date and Hour of Occurrence	04/17/2010 09:30	Date and Hour of Discovery	Same
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Brandon Powell		
By Whom?	Kelly Hart	Date and Hour	04/19/2010 13:00		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	-		

RCVD APR 28 '10

If a Watercourse was Impacted, Describe Fully.\*  
N/A

OIL CONS. DIV.  
DIST. 3

Describe Cause of Problem and Remedial Action Taken.\*

During startup operations, the shaft seal of the gas powered compressor starter leaked gas into the compressor skid area. The gas/air mixture found an ignition source, most likely the spark plug wires. This starter has been replaced and starters on units in other locations are undergoing inspection.

Describe Area Affected and Cleanup Action Taken.\*  
No cleanup required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kelly K Hart</i>	OIL CONSERVATION DIVISION		
Printed Name: Kelly K Hart	Approved by District Supervisor: <i>Brandon Powell</i>	For: CP	
Title: Operations Center Manager	Approval Date: 9/28/10	Expiration Date:	
E-mail Address: kelly.hart@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 04/27/2010	Phone: 505-326-9444		

\* Attach Additional Sheets If Necessary

WBP1027142397