District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

						OPERATOR			☐ Initial Report ☐ Final Report			
Name of Company Huntington Energy, L.L.C.						Contact David Herritt						
Address 908 N.W. 71st St., Oklahoma City, OK 73116						Telephone No. 405-840-9876						
Facility Name Ute Mountain Ute #82						Facility Type Producing Well						
Surface Own	ner: Ute M	Iountain Ute	Tribe	Mineral O	wner: \	Ute Mounta	n Ute Tribe		Lease N	o. I-22-IN	D-2772	
LOCATION OF RELEASE 30-645-34387											1387	
									ast/West Line County			
L	22	32N	14W	1570	South		1035	West		San Juan		
Latitude_36.97051 Longitude108.30194												
NATURE OF RELEASE												
Type of Release Condensate							Volume of Release 26 bbls Volume Recovered 0 bbls					
Source of Rel	ease Tank	Battery			Date and Hour of Occurrence: Date and Hour of Discovery 9:00 am							
337 T 1'	4- NI-4' C	7:0		May 24, 2010 6:00 am - approx May 24, 2010								
Was Immediate Notice Given? (24 hrs) ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Ute Mountain Ute Environmental, BIA, BLM, NMOCD						
By Whom? Catherine Smith Was a Watercourse Reached?						Date and Hour 5/24/2010 approx. 2:00 pm If YES, Volume Impacting the Watercourse.						
(Dry Sand) Yes No						ROVD MAY 27 '10						
If a Watercourse was Impacted, Describe Fully.* N/A OIL CONS. DIV.											. DIV.	
DIST. 3											ij	
Describe Cause of Problem and Remedial Action Taken.* Dump valve on separator hung open allowing well to flow to oil tank resulting in latch on tank opening and blowing out the top of tank into dike area – approx 26 bbls contained in dike. Action taken: Immediate notification. Replaced latch and put in new seals.												
Describe Area Affected and Cleanup Action Taken.* Dike: approximately 8' x 20'. Ron Lackey, company representative, contacted IEI. Approximately 7 yds of dirt removed from site. Dike rebuilt. Location cleaned up on May 25, 2010.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
/	1)			OIL CONSERVATION DIVISION								
Signature:	athen	ne S			a a Frital							
Printed Name	: Catherine	e Smith		4	Approved by District Supervisor: Branch Tell For: CP							
Title: Regula	tory		-		Approval Date: 9/28/10 Expiration Date:							
E-mail Address: csmith@huntingtonenergy.com						Conditions of Approval:				Attached	Attached	
Date: 5/25	/2010	Phone	e: 405-84	0-9876 ext. 129								