

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	1
LAND OFFICE	1
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
		5. State Oil & Gas Lease No.
		7. Unit Agreement Name
		8. Farm or Lease Name Bullseye
		9. Well No. 2
		10. Field and Pool, or Wildcat Wildcat-Dakota
		12. County McKinley
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		
2. Name of Operator Fairfax Exploration Inc.		
3. Address of Operator 301-B Graceland S.E. Albuquerque, N.M. 87108		
4. Location of Well UNIT LETTER <u>N</u> <u>540</u> FEET FROM THE <u>south</u> LINE AND <u>1560</u> FEET FROM THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>16 N</u> RANGE <u>9 W</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.) 7244 GR		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input checked="" type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set GO Elite 4 1/2" bridge plug @ 1960'.
Set Guiberson 4 1/2" cast iron plug @ 930'.
Set valve and bull plugs on top of 4 1/2" casing at surface.
Place appropriate sign stating that well is temporarily abandoned.
(As per instructions by phone from E.C. Arnold.)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE President DATE Sept. 13, 1974

APPROVED BY [Signature] TITLE SUPERVISOR DATE SEP 24 1974

CONDITIONS OF APPROVAL, IF ANY: