

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. 09-000167
2. NAME OF OPERATOR Amerada Hess Corporation	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache
3. ADDRESS OF OPERATOR Drawer "D", New Mexico 88265	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 890' FSL & 890' FWL	8. FARM OR LEASE NAME J. Apache "I"
	9. WELL NO. 4
	10. FIELD AND POOL, OR WILDCAT Lindrith Gallup Dakota
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, T23N, R3W
14. PERMIT NO.	12. COUNTY OR PARISH Rio Arriba
15. ELEVATIONS (Show whether DF, HT, OR, etc.) 7205' GR	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRAC TURE TREAT	<input type="checkbox"/>	FRAC TURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	<input type="checkbox"/>

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

August 1, 1984 to August 4, 1984 - Pulled rods, pump and tbg. Perf. 5-1/2" csg. opposite Dakota zone f/7271 to 7277' and f/7322 to 7328' w/4 SPF. Ran stress fracturing tool and set f/7324 to 7336'. Set off stress fracturing tool. Trip out and ran stress fracturing tool and set f/7271 to 7277. Set off stress fracturing tool. Ran gauge ring and junk basket on wire line to 7221'. Re-ran tbg., and hot oiled same. Ran pump and rods and resumed production. Presently pumping load oil.

RECEIVED
SEP 07 1984
OIL CON. DIV.
DIST. 3

RECEIVED
AUG 23 1984
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Donnell Green TITLE Production Clerk DATE 8-6-84

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE AUG 22 1984

CONDITIONS OF APPROVAL, IF ANY: NMOCC

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

FARMINGTON RESOURCE AREA

BY ESB