## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Dec. 1973	Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NOO-C-14-20-5607
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil 😡 gas 🗇	South Blanco Navajo 8
well Well other	9. WELL NO.
2. NAME OF OPERATOR	#1
Mesa Petroleum Co.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 80264	Lybrook Gallup Ext.
1660 Lincoln Street, Suite 2800, Denver, CO	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec. 8-T23N-R7W
AT COTTO	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba New Mexico
AT TOTAL DEPTH:	1 14. API NO.

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

15. ELEVATIONS (SHOW DF, KDB, AND WD) 71781 GL

SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE Report results of multiple completion or zone REPAIR WELL hange on Form 9-330.) PULL OR ALTER CASING U. S. GEOLOGICAL SURVEY. MULTIPLE COMPLETE CHANGE ZONES FARMINGTON, N. M. ABANDON\* (other) Spud & test BOT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The above well spudded at 2:00 PM December 28, 1980. A  $12\frac{1}{4}$ " hole was drilled to 263' KB. 8 5/8" 24#/ft K-55 STC (new) casing was set at 255' KB and cemented with 200 sxs Class "B" plus 2% CaCl. Plug was down at 8:15 FM with good returns. Circulated 14 bbls of cement slurry to the surface.

The surface casing and BOP stack was tested to 1000 psi for 30 minutes prior to drilling the surface casing shoe. The test held OK.

Subsurface Safety ig is true and correct 18. I hereb TITLE Div. Drlg. Supervisor December (This space for Federal or State office use) DATE

JAN 0 7 1981

APPROVED TED HOW TELL KIND

ARM/NGTON DISTRICT

\*See Instructions on Reverse Side