

APPROVED

MAR 4 1956

Budget Bureau No. 42-R-350.2.  
Approval expires 12-31-55.Form 9-331b  
(April 1952)

(Orig. Sgd.) J. W. LONG

(SUBMIT IN TRIPLICATE)

Indian Agency NavajoAlottedAllottee Oil in hole - ex. FormLease No. 11-20-603-50

ACTING DISTRICT ENGINEER		

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASINGS	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 14, 1956

Well No. 1 is located 550 ft. from N line and 990 ft. from W line of sec. 22Sec. 22  
(1/4 Sec. and Sec. No.)22 North 6 West  
(Twp.) (Range)U. T. P. M.  
(Meridian)Willcox

(Field)

Sandoval

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is 7573 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

A 100' cement plug set from 6325-6425 w/80 sz. 1400' of 10-3/4" 32.75# cang. cemented w/175 sz. left in hole. 6310' of 15.50# 5 1/2" cang. cemented w/250 sz. 1 ft in hole. A cement plug set from surface to 92' w/50 sz. & space between 5 1/2" & 10-3/4" cang. filled w/cement. A marker 5' above the surface of ground & 5 1/2" in dia. filled with cement.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company PLYMOUTH OIL COMPANYAddress 340 Silver State BuildingDenver 2, Colorado

By Curtis Hancock  
Curtis Hancock  
Regional Supervisor

Title