
N		UNITED STATES SUBMIT IN TRIPLICATE* Other instructions on red DEPARTMENT OF THE INTERIOR verse side)		E* 5.	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.		
	SUNDRY NO	OTICES AND REPORTS roponals to drill or to deepen or plug LICATION FOR PERMIT—" for such	ON WELLS	<i>n</i> .	NM-28241 IF INDIAN, ALLOTTER		
1.	OIL X GAS OTHE	R	nin al Buc Franc		UNIT AGREEMENT NA	KE	
<u>2.</u>	NAME OF OPERATOR				8. FARM OR LEASE NAME		
	MERRION OIL & GA		Federal Media				
3.	ADDRESS OF OPERATOR	9.	WELL NO.				
	P O. Box 840. F	armington, NM 87499		į	6		
4.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface H 1590 FNL & 570 FEL				Undesignated Mesawerds 11. SEC. T. B., M., OR REE. AND SURVEY OF AREA Sec 22, T19N, R3W		
14.	PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12	COUNTY OR PARISH	13. STATE	
		6853' GL			Sandoval	NM	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data						
	NOTICE OF INTENTION TO:			equent	TENT REPORT OF:		
	TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	\blacksquare	REPAIRING W		
	FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT		ALTERING CA		
	SHOOT OR ACIDIZE	ABANDON*	SECOTING OR ACIDIZING		ABANDON MEN	T	
	EPAIR WELL CHANGE PLANS (Other) (NOTE: Report re				ults of multiple completion on Well		
	(Other)	Other) Completion or Recom					
17.		O OPERATIONS (Clearly state all perting rectionally drilled, give subsurface losses)	ant details and give pertinent day	tes inc	juding estimated date	of starting an	

The proposed P&A was completed on 12/7/90. Attached is a well history for your records.



SIGNED George F. Sharpe	TITLE Engineer		DATE 12-17-90
Title (Title) or Chair offer men)	AREA MANAGER RIO PUERCO RESOURCE NMOCD *See Instructions on Reverse Side	AREA Copies:	Taxes - 1 Acct - 1 Land - 1 BLM - 6 Rio Puerco Well File - 1

FEDERAL MEDIA NO. 6

December 6, 1990 Day No. 1

Summary: Start plugging procedure.

Detail: Move Bedford on location and RU. NU BOP. Tally and pickup 2-3/8" tbg. Tag fill @ 1640'. Circ dn to 1660'. Could not clean out to PDTD. Spot a 25 sk cement plug from 1660' to 1340'. Pull above cement. WOC. SDON. (ARM)

Off Report

December 7, 1990 Day No. 2

Summary: Finish plugging procedure.

Detail: TIH. Tag cement @ 1316'. Mix 9.0 ppg mud. Roll hole w/ mud. Pull tbg to 428'. Spot a 30 sk cement plug to surface. Pumped 13 sx cement dn annulus. Cut off surface csg. Install dry hole marker. RDMO. (ARM)