Form 3160-5 (November 1983) (Formerly 9-331)

18.

## UNITED STATES SUBMIT IN TRIPLICATE\* Other instructions on reverse aide)

6993' KB

Form approved.	
Budget Bureau No.	1004-013
Expires August 31,	1985

5. LEASE DESIGNATION AND SECIAL NO.

NM-37548	

BUREAU OF LAND MANAGEM	NM-37548	
SUNDRY NOTICES AND REPORT (Do not use this form for proposals to drill or to deepen or use "APPLICATION FOR PERMIT—" for s	plug back to a different reservoir!	6. IF INDIAN, ALLOTTEE OR TRIBE NAME  N/A
OIL XX GAS OTHER	87 AUG -3 AH 9:34	7. UNIT AGREEMENT NAME N/A
2. NAME OF OPERATOR		
Gary-Williams Oil Producer, Inc.	FARMESTON RESOURCE ARE	San Isidro 1
3. ADDRESS OF OPERATOR	TEXICO	9. WELL NO.
115 Inverness Drive East, Englewood, CO	80112-5116	16
<ol> <li>LOCATION OF WELL (Report location clearly and in accordance with See also space 17 below.)</li> </ol>	any State requirements.*	10. FIELD AND POOL, OR WILDCAT
At surface		Rio Puerco Mancos
510' FSL and 565' FEL (SE SE) Section 1-	T2ON-R3W	11. SEC., T., E., M., OR RLE. AND SURVEY OR ARMA
(0)		SE SE 1-T20N-R3W
14. PERMIT NO. 15. ELEVATIONS (Show whether	Der DF, KT, GK, etc.)	12. COUNTY OR PARISH 13. STATE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

<u></u>	[]		_
TEST WATER SHUT-OFF PU	CLL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	BANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL CE	HANGE PLANS	(Other)	
(Other) Request Long Term	Shut In Status	(Note: Report results of mul Completion or Recompletion B	tiple completion on Well eport and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) •

Gary-Williams Oil Producer, Inc. ("GWOP") respectfully requests permission for a long term shut in status for the above mentioned well. A stripping job would be required to return this well to production. Current production and economics do not justify payout on stripping job.

There are no known problems with the casing integrity due to the fact that the cement was circulated to surface and the casing is less than 5 years old. Because of the existing condition of the well, GWOP requests that the testing requirements be waved at this time.

In the absence of an approved suspension, there may be a premature abandonment of the well and resulting loss of recoverable reserves.



Sandova1

SUBSECUENT REPORT OF :

	7.0	20 1207		
SIGNED AMPLY THAT THE	foregoing is true an Offect Co	ST. Compliance	Administrator	DATE 7/31/87
(This space for Federal		'ITLE		DATE
CONDITIONS OF APPROVAL, IF ANY:	OVAL, IF ANY:			

\*See Instructions on Reverse Side NMOCC