Budget Bureau No. 1004-0135 Form 3160-5 UNITED STATES SUBMIT IN TRIPLICATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side) Expires August 31, 1985 (November 1983) 5. LEASE DESIGNATION AND SERIAL NO. (Formerly 9-331) BUREAU OF LAND MANAGEMENT NOO-C-14-20-5831 8. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (No not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals. AllottedUNIT AGREEMENT NAME WELL GAN WELL OTHER **1 3** 1986 S. PARM OR LEASE NAME NAME OF OPERATOR DIAMOND SHAMROCK EXPLORATION COMPANY Penistaja Federal ADDRESS OF OPERATOR BUREAU OF LAND MANAGEMENT LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface **FARMINGTON RESOURCE AREA** 10. PIELD AND POOL, OR WILDCAT Gallud 11. sec., T., R., M., OR BLK. AND SURVEY OR ARMA 2160' FNL & 1930' FWL Section 14, T20N, R4W 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. Sandoval New Mexico 6871' GR

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBERQUENT REPORT OF:
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF REPAIRING WELL
FRACTURE THEAT		MULTIPLE COMPLETE		FRACTURE TREATMENT ALTERING CASING
RHOOT OR ACIDIZE	X_	ABANDON*		SHOOTING OR ACIDIZING ABANIMMENT.
REPAIR WELL (Other)		CHANGE PLANS		(Other)  (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and gones pertinent to this work.) \*

DIAMOND SHAMROCK EXPLORATION COMPANY requests permission to perforate and test 2 more intervals. If approval is received the following will be carried out.

- 1. Pull out of the hole with rods and tubing.
- 2. Perforate at 4142-47 and 4156-62 and breakdown.
- 3. Swab test zones.
- 4. If productive, return well to pumping operations.

If not productive, permission to plug and abandon the well will be requested.

ON CONDITIONS OF APPROVAL, IF ANY:

AMAR 201986

CONDITIONS OF APPROVAL, IF ANY:

MAR 201986

TITLE Production Engineer

ATB 3-10-86

MAR 201986

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: