

January 9, 2001
Santa Fe Leggs
0-11-21M-10W



Cement Bottom from Water injection Tank

January 9, 2001
Santa Fe Leggs
0-11-21N-10W




Tank Bottoms from water Injection Tank
2 loads sent to Oil Reclaimer

January 9, 2001
Santa Fe Leggs
0-11-21N-10W



Tank Bottoms from water Injection Tank
Sent to Oil Reclaimer



February 23, 2001

Santa Fe Leggs

0-11-21W-10W


Facing East
across overflow
pit site

Final Inspection

February 23, 2001
Santa Fe Leggs
0-11-21W-10W

Facing SE
across overflow
pit site


Final Inspection



February 23, 2001
Santa Fe Leggs
0-11-21W-10W

Facing East
across injection
building site

Final Inspection




Santa Fe Leggs
0-11-21N-10W

February 23, 2001

Looking NE across
injection building site

Final Inspection



February 23, 2001
Santa Fe Leggs
0-11-21N-10W

Tank Battery site in
foreground
Looking south across
land farm

Final Inspection



Santa Fe Leggs
February 23, 2001
O-11-21W-10W

Land farm

Final Inspection