



# OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO  
1000 RIO BRAZOS RD. - AZTEC

87410

LAND COMMISSIONER  
PHIL R. LUCERO

DIRECTOR  
JOE D. RAMEY



STATE GEOLOGIST  
EMERY C. ARNOLD

August 30, 1976

Mr. George T. Slaughter  
Petroleum Consultants, Inc.  
1420 Carlisle Blvd. S. E.  
Albuquerque, New Mexico 87110

Re: Petroleum Consultants, Inc.  
Connie #5  
G-21-24N-7W

Dear Mr. Slaughter:

The attached form C-103 for the subject well is not approved.

Rule 108 requires the operator of a well with defective casing to proceed with diligence to repair or to plug the well.

If remedial action to repair the casing has not commenced by September 15, 1976, a case will be requested to allow all interested parties to appear and show why the well should not be properly plugged and abandoned.

If there are questions, please contact us.

Yours very truly,

*A. R. Kendrick*  
A. R. Kendrick  
Supervisor, District #3

ARK:mc

Attachment

xc: OCC, Santa Fe  
USGS, Durango