٠.				
		ļ	<u> </u>	<u> </u>
ı		ĺ	1	İ
ł		ļ		ļ
ĺ	!			
I			- <b>-</b>	
۱				

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No. 42-R358. Approval expires 12-31-60.	.4.
--	-----

Land Office State Pe

Lease No. 0766777

Unit Carryon Largo Unit

MOTICE OF INTENTION TO DRILL		auno-		
NOTICE OF INTENTION TO DRILL  NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF WAT	ER SHUT-OFF	
NOTICE OF INTENTION TO TEST WATER SHUT-	OFF	SUBSEQUENT REPORT OF SHOO	TING OR ACIDIZING	
NOTICE OF INTENTION TO RE-DRILL OR REPAI	D WELL	SUBSEQUENT REPORT OF ALTE	RING CASING.	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	WELL	SUBSEQUENT REPORT OF RE-D	RILLING OR REPAIR	
NOTICE OF INTENTION TO PULL OR ALTER CAS	SING	SUBSEQUENT REPORT OF ABAN	DONMENT	
NOTICE OF INTENTION TO ABANDON WELL	X a	SUPPLEMENTARY WELL HISTOR	Υ	
(INDICATE ABOVE	BY CHECK MARK NAT	URE OF REPORT, NOTICE, OR OTHE	P DATA)	
			·	
		March	139	, 19.52
ell No. 72 is located 20	6 4 C []			, . , -1-1-1
ll No. 72 is located 80		$\int \lim and \frac{100}{100}$ ft. fr	om $W$ line of sec	: 11
Sec. 11	CAN (	H.S.K.W	( )	
	wp.) (Ran			
Otero P.C. Bat.	Rio Arr	150	ow Marico	
(Licht)	(County or Sub	division)	(State or Territory)	
elevation of the derrick floor ab	ove sea lovel :	6638 c		
action hour ap	ove sea level 1	s it.		
	DETAILS	OF WORK		
e names of and expected depths to objective s ing po	ands: show sizes			
ing po	oints, and all other i	ights, and lengths of proposed cas mportant proposed work)	ings; indicate mudding jo	obs, cement-
It is intended to salvame	casing and	15 T 1 2 Star Statement of the Statement of		
It is intended to salvage	casing and	plug and abendon ti	is well in the	follow
It is intended to salvage maner:  1. Cover Pictured 33	casing and	plug and abendon th	is well in the	follow
1. Cover Pictured Cl 2. Shoot off and rec	iffe peri.	v/50 sacks coment.		: follows
1. Cover Pictured Cl 2. Shoot off and rec	iffe peri.	v/50 sacks coment.		follow
2. Shoot off and rec 3. Set coment plug f	iffe peri.	w/50 sacks coment.		follow
2. Shoot off and rec 3. Set coment plug i 4. Plug surface w/b0	iffs perf. over 1950 for ros 5 1/2   secks comes	w/50 sacks coment.		rollor
2. Shoot off and rec 3. Set coment plug i 4. Plug surface w/b0	iffe peri.	w/50 sacks coment.		rollow
2. Shoot off and rec 3. Set coment plug i 4. Plug surface w/b0	iffs perf. over 1950 for ros 5 1/2   secks comes	w/50 sacks coment.		rollows
3. Set coment plug i	iffs perf. over 1950 for ros 5 1/2   secks comes	w/50 sacks coment.	*:  RECEIV	ÎD)
2. Shoot off and rec 3. Set coment plug i 4. Plug surface w/b0	iffs perf. over 1950 for ros 5 1/2   secks comes	w/50 sacks coment.		ÎD)
2. Shoot off and rec 3. Set coment plug i 4. Plug surface v/40 5. Place h' x h' mar	iffs perf. over 1950 for 1950	w/50 sacks coment. bet of 5 1/2" casin casing stub to 1679 at.	RECEIVE MAR 23 19	ÎD)
2. Shoot off and rec 3. Set coment plug i 4. Plug surface v/40 5. Place h' x h" mar	iffs perf. over 1950 for 1950	w/50 sacks coment. bet of 5 1/2" casin casing stub to 1679 at.	RECEIVE MAR 23 19	ÎD)
1. Cover Pictured CR 2. Shoot off and rec 3. Set coment plug f 4. Plug surface v/40 5. Place h' x h" mar	iffs perf	w/50 sacks coment. bet of 5 1/2" casin casing stub to 1679 at.	RECEIVE MAR 23 19	ÎD)
2. Shoot off and rec 3. Set coment plug i 4. Plug surface v/40 5. Place h: x h" mar  aderstand that this plan of work must receive	iffs perf	w/50 sacks coment. bet of 5 1/2" casin casing stub to 1679 at.	RECEIVE MAR 23 19	ÎD)
2. Shoot off and rec 3. Set coment plug i 4. Plug surface w/w 5. Place h' x h' mar  anderstand that this plan of work must receive pany  Box 997	over 1950 for 1950 fo	w/50 sacks coment. bet of 5 1/2" casin casing stub to 1679 at.	RECEIVE MAR 23 19	ÎD)
2. Shoot off and rec 3. Set cament plug i 4. Plug surface v/40 5. Place h' x h' mar  maderated that this plan of work must receive pany El Pago Matural Gas Co	over 1950 for 1950 fo	w/50 sacks coment. bet of 5 1/2" casin casing stub to 1679 at.	MAR 23 IS OIL CON. O DIST. 3	ÎD)