

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

66

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla 28

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT
Undesignated Gallup
Undesignated Dakota11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 34, T25N, R4W

12. COUNTY OR PARISH 13. STATE

Rio Arriba

New Mexico

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

152 North Durbin, Casper, Wyoming 82601

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

485' FNL 760' FWL (Unit Letter "D")

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6909' Gr., 6922' RB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☒

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 7625', PBTD 7590'. 8 5/8" casing at 235'. 5 1/2" casing at 7625'. Perforated 6493-6683' and 7354-7552'. Well shut-in.

We propose to repair casing leak in 14# section of 5 1/2" casing between 680' and 3183' as follows. If casing freepoint is located below leak(s) and is above the Pictured Cliffs formation (3160'), the casing will be cut-off, pulled, and a pack-off casing bowl will be run. If freepoint is above leak(s) or below the top of the Pictured Cliffs formation, the casing will be repaired with cement using a low pressure balanced column method to seal the leak. Well will be returned to production.



USGS-Durango(5) File

18. I hereby certify that the foregoing is true and correct

SIGNED

J. A. Ullman

TITLE Administrative Supervisor

DATE 11-23-70

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side