

J 10-2-72 30-039-20568

F. Loc. 870/N; 790/W Elev. 6737' ir. Spd. 10-25-72 Comp. _____ TD _____ PB _____
 Casing S. 878 @ 401 W 350 Sx. Int. _____ @ _____ W _____ Sx. Pr. 5 1/2 @ 5402 W 250+ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. SWF

T
R
A
N
S

I.P. _____ BO/D _____ MCF/D After _____ Hrs. _____ SICP _____ PSI After _____ Days GOR _____ Grav. _____ 1st Del. _____ \$ _____

TOPS

NITD

X

Well Log

TEST DATA

Kirtland	C-103	✓✓	Plat	X	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	C-104		Electric Log								
Pictured Cliffs		1 3/4°	C-122								
Cliff House	Ditr		Dfa								
Menefee	Datr		Dac								
Point Lookout	160 A.										
Mancos											
Gallup											
Sanostee											
Greenhorn											
Dakota											
Morrison											
Entrada											

P
O

OteroChacraCo. RA s 9 T 25N R 5W U D Oper. Amoco Prod. Co. Lse. Jic. Cont. 146 No. 23