Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0/35 Expires: November 30, 2000

5.	Lease Serial No.	/
	JIC CONTRACT	148

SUNDRY NOTICES AND REPORTS ON WEL	
Do not use this form for proposals to drill or to re-e	nter an
abandoned well. Use form 3160-3 (APD) for such pro	

abandoned well. Use form 3160-3 (APD) for such proposals.				6.	6. If Indian, Allottee or Tribe Name JIC APACHE		
SUBMIT IN TRI	PLICATE - Other instruc	ctions on reverse	side.	7.	If Unit or C	A/Agreem	ent, Name and/or No.
Type of Well Oil Well	ner			8.	Well Name JIC APAC		7
2. Name of Operator Contact: CHERRY HLAVA BP AMERICA PRODUCTION COMPANY E-Mail: hlavacl@bp.com				9.	9. API Well No. 30-039-23786		
3a. Address P.O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (inclue) Ph: 281.366.408 Fx: 281.366.0700	1	10	10. Field and Pool, or Exploratory W. LINDRITH GALLUP-DAKOTA			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		1	. County or	Parish, and	d State
Sec 13 T25N R05W NENW 9	90FNL 1660FWL				RIO ARR	IBA COL	JNTY, NM
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NAT	URE OF N	OTICE, REPO	ORT, OR	OTHER	DATA
TYPE OF SUBMISSION			TYPE OF	ACTION			
T Notice of Learns	☐ Acidize	Deepen		□ Production	(Start/Resu	ime)	■ Water Shut-Off
Notice of Intent	☐ Alter Casing	☐ Fracture 7	reat	☐ Reclamation	n		■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	☐ New Cons	truction	☐ Recomplete	e		☐ Other
☐ Final Abandonment Notice	☐ Change Plans	Plug and a	Abandon				
	☐ Convert to Injection	☐ Convert to Injection ☐ Plug Back		☐ Water Disp	osal		
On 11/12/2001 Amoco Producto the 4th quarter of 2002. Peour P&A NOI and procedure. BP America Production Compressed integrity test. It is future Saltwater Disposal con	ermission was granted 11 coany requests permission our intent to hold the well version.	/16/01. We respect	tfully reque: andon the w	st to withdraw rellbore and pe			
14. I hereby certify that the foregoing i	For BP AMERICA P	RODUCTION COMP	ANY, sent to	the Rio Puerc	0	\/F	· · · · · · · · · · · · · · · · · · ·
Name(Printed/Typed) CHERRY	HLAVA (hvrry f	Hava Title	AUTHO	RIZED REPRI	SENTATI	VE	
Signature (Electronic	Submission)	Date	05/01/2	002			
	THIS SPACE FO	OR FEDERAL O	R STATE	OFFICE USE			
/s/ Patric	ia M. Hester	Land	sænd Min	eral Resourc	tes	Date	MAY 1 4 2002
Conditions of approval, if any, are attached certify that the applicant holds legal or eqwhich would entitle the applicant to conditions.	uitable title to those rights in th	e subject lease	Office				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	3 U.S.C. Section 1212, make it a statements or representations a	a crime for any person l s to any matter within i	nowingly and s jurisdiction.	willfully to make	to any depar	tment or a	gency of the United

San Juan Basin Well Work Procedure

Well Name: Version: Date: Budget: Repair Type:	Jicarilla Contract #1 3/25/2002 DRA TXA	148- 37		
Objectives:				
1. TXA wellt SWD con	oore and perform mechanica version.	il integrity test. Hold for	rehabilitation of t	he GP/DK or future
Pertinent Info				
Location:	Sec 13 T25N R5W		Horizon: API #:	Basin Dakota
County: State:	Rio Arriba New Mexico		Engr:	30-039-23786 Allen Kutch
Lease:	New Mexico		Phone:	(281)366-7955
Formation Top	os: (Estimated formation top			
Nacimento:		Menefee:		
Ojo Alamo:		Point Lookout:		
Kirtland Shale:		Mancos Shale		
Fruitland:		Gallup:	6998	
Pictured Cliffs:		Graneros:	7000	
Lewis Shale:	4540	Dakota: Morrison:	7836	
Chacra: Cliff House:	4540	MOTISON:		
Bradenhead T	est Information: \(\) Tubing:	Casing:	BH:	
rest Date.	rubnig.	Casing.	DII.	
Time BH	CSG	INT CSG		
5 min				
10 min				
15 min				
Comments:				
Comments.				

Temporary abandonment procedure

- 1. Contact Federal and State agencies prior to starting work (NMOCD Charlie Perrin, 505-334-6178 X16, BLM Brian Davis 505-761-8756).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 4. Blow down well and kill well, if necessary, with lease water.
- 5. ND wellhead. NU BOP's.
- 6. POOH with 2-7/8" tbg, visually inspecting.
- 7. Make bit x scraper run.
- 8. TIH with CIBP on tbg. Set CIBP at 6950'.
- 9. Load csg with inhibited lease water.
- 10. Attach chart recorder. Test casing to 550 psi for 30 minutes. Fax copy of chart to 281-366-0700, attention Allen Kutch.
- 11. RIH with 2-7/8" tbg. ND BOP, NU WH.
- 12. RDMO SU.

Jicarilla Contract 148-37 - Proposed TXA Configuration 3-25-2002 Rio Arriba County, NM ATK Unit C Section 13 T25N - R5W Run 65

