(November 1983) (Formerly 9–331 DEPARTM BUREAL	JNITED STATES SENT OF THE INTERIO J OF LAND MANAGEMENT CES AND REPORTS OF COMMENT OF THE PROPERTY OF SUCH PERMIT—" for such property or such property of suc	N WELLS	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. NM - 0555076 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.			7. UNIT AGREEMENT NAME
WELL X WELL OTHER			S. FARM OR LEASE NAME
2. NAME OF OPERATOR			Howard Federal
Reading & Bates Petroleum Co.			9. WELL NO.
2200 Mid-Continent Tower, Tulsa, OK 74103			43-15 10. FIELD AND POOL, OR WILDCAT
4. LOCATION OF WELL (Report location cl See also space 17 below.) At surface	early and in accordance with any St	"RECEIVED	Gavilan-Mancos/ Gavilar Greenhorn-Graneros/Dakota
1650'FSL, 790'FEL		MAR 2 8 1986	Sec. 15, T25N, R2W
14. PERMIT NO. 15. ELEVATIONS (Show whether DEBUREAUTOF LAND MANAGEMENT			N.M. P.M. 12. COUNTY OR PARISH 18. STATE
12. FBROIL NO.	7249 'GL F	ARMINGTON RESOURCE AREA	Rio Arriba NM
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: REPAIRING WELL			
	PCLL OR ALTER CASINO	WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CASING
FRACIORE INDEA	MULTIPLE COMPLETE	SHOOTING OR ACIDIZING	ABANDONMENT*
BROOT OF RELEASE	ABANDON®	Course Running & C	mtg. surface csg.
REPAIR WEDD		Completion or Recomp	of multiple completion on Well letion Report and Log form.)
On 12-7-85, ran surface casing in 12½" hole as follows: Drilled depth 381'. Ran 9 joints 9-5/8", 36#, K-55, STC casing to 374'. Cemented with 250 sx. Class "B" + 3% CaCl ₂ + 1/4#/sx. flocele. Bumped			
plug at 4:40 A.M., 12-7-85. Good returns throughout job. Circulated			
approx. 10 bbls. cement to reserve pit. Cement stood at ground level.			
			RECEIVED APR 1 0 1986
			OIL CON. DIY