

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Bureau Form No. 1001-101
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
TENNECO OIL COMPANY

3. ADDRESS OF OPERATOR
P.O. BOX 3249, ENGLEWOOD, CO 80155

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
960' FNL, 960' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether by **BUREAU OF LAND MANAGEMENT** or other)
6652' -GR FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.
CONTRACT #108

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
JICARILLA

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
JICARILLA C

9. WELL NO.
5M

10. FIELD AND POOL, OR WILDCAT
BASIN DAKOTA/BLANCO MV

11. SEC., T., R., N., OR BLK. AND SURVEY OR AREA
SEC 24, T26N, R5W

12. COUNTY OR PARISH
RIO ARRIBA

13. STATE
NM

RECEIVED
MAY 14 1986

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	
(Other) SINGLE PRODUCER		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TENNECO REQUESTS PERMISSION TO T & A THE MESAVERDE ZONE ON THE REFERENCE WELL ACCORDING TO THE ATTACHED DETAIL PROCEDURES.

RECEIVED
MAY 21 1986
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE SR. ADMINISTRATIVE ANALYST DATE 5/8/86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE MAY 19 1986

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
DATE
FOR AREA MANAGER

*See Instructions on Reverse Side

NMOCC

934z/2/JJE
 LEASE Jicarilla C
 WELL NO. 5M

CASING:

9 5/8 "OD, 36 LB, K-55 CSG/W 200 SX

TOC @ surf . HOLE SIZE 12 1/4 DT: 6/3/80

REMARKS

7 "OD, 23 LB, K-55 CSG/W 300/800 SX

TOC @ . HOLE SIZE 8 3/4 DT: 6/13/80

REMARKS DV @ 4723 No circ 1st stg Lost circ
 2nd stage

4 1/2 "OD, 10.5/11.6 LB K-55 CSG.W/ 300 SX

TOC @ 5661 . HOLE SIZE 6 1/4 DATE 6/21/80

REMARKS TOL @ 5661

TUBING:

2 3/8 "OD, 4.7 LB, J-55GRADE, 8 RD, Beveled CPLG

LANDED @ 7403 , Packer @ 7390

FN @ 7397

DETAILED PROCEDURE:

1. MIRUSU. Kill well w/1% KCL wtr. NDWH. NUBOP.
2. Run freepoint in 2-3/8" tbg. RIH w/ chemical cutter and cut 2-3/8" tbg as low as possible. POOH w/ 2-3/8" tbg, blast joints and Bowen tbg patch, laying down perforated tbg, tbg patch, cut tbg and blast joints.
3. RIH w/ washover shoe and washover pipe on 2-3/8" tbg. Washover tbg w/nitrogen foam. POOH w/tbg and washover tools.
4. RIH w/overshot and jars on 2-3/8" tbg. Latch fish and POOH. Lay down Model "L" sliding sleeve.
5. RIH w/muleshoe, F Nipple, spacer tube, seal assembly, locator, and 2-3/8" tbg. Land longstring in Model "F-1" production packer.
6. NDBOP. NUWH. Swab in Dakota if necessary. RDMSU.

