

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE  
(Other instructions on reverse side)

EXPIRES AUGUST 31, 1985  
5. LEASE DESIGNATION AND ACREAL NO.

SF-079186

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

OIL WELL  GAS WELL  OTHER

OCT 16 1986

2. NAME OF OPERATOR

Caulkins Oil Company BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

3. ADDRESS OF OPERATOR

P.O. Box 780 Farinington, New Mexico 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

990' F/N and 1120' F/W

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, AT, CR, etc.)

6572 GR

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Breech "E"

9. WELL NO.

50-E

10. FIELD AND POOL, OR WILDCAT

Blanco Mesa Verde - Basin Dakota

11. SEC., T., R., W., OR BLK. AND SURVEY OR AREA

Section 5, 26 North 6 West

12. COUNTY OR PARISH 13. STATE

Rio Arriba

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF   
FRACTURE TREAT   
SHOOT OR ACIDIZE   
REPAIR WELL   
(Other)

PULL OR ALTER CASING   
MULTIPLE COMPLETE   
ABANDON\*   
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF   
FRACTURE TREATMENT   
SHOOTING OR ACIDIZING   
(Other) Repair Packer Leak

REPAIRING WELL   
ALTERING CASING   
ABANDONMENT\*

(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and cones pertinent to this work.)

- 10-1-86 Moved in Rig. Killed well with water, pulled 2 1/16" Mesa Verde tubing.  
Pulled 2 1/16" Dakota tubing with packer. Found leak in tubing one joint above packer.
- 10-2-86 Replaced bad joint. Redressed packer, re-run tubing.  
Reset tubing and packer same as previously set.
- 10-10-86 Packer tests now underway show good separation.

RECEIVED  
OCT 23 1986  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Charles E. Weyan TITLE Superintendent DATE 10-14-86

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

OPERATOR