Form 3160-5 (June 1990)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMEN		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NMNM61	
Do not use this	SUNDRY NOTICES AND REPORTS ON form for proposals to drill or to deepen or reer Use "APPLICATION FOR PERMIT—" for such	ntry to a different reservoir.	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation		
1. Type of Well Oil X Gas Well 2. Name of Operator		7	8. Well Name and No. Chaco Plant #36 9. API Well No.	
3. Address and Telephone 7415 E. M	No.C/O Walsh Engr. & Prod. Corp.		10. Field and Pool, or Exploratory Area Basin Fruitland Coal	
Unit F, 1 Section 3	450'FNL & 1450'FWL 6, T26N, R12W		11. County or Parish, State San Juan County, N.M.	
12. CHECK	APPROPRIATE BOX(s) TO INDICATE NA		T, OR OTHER DATA	
TYPE OF	SUBMISSION	TYPE OF ACTION		
X Notice	Recomp	olction	Change of Plans New Construction Non-Routine Fracturing	
	Casing	-	Water Shut-Off Conversion to Injection	
	Other _		Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
Describe Proposed or C give subsurface to	ompleted Operations (Clearly state all pertinent details, and give pertine cations and measured and true vertical depths for all markers and zon	ent dates, including estimated date of starting les pertinent to this work.)*	any proposed work. If well is directionally drilled,	

J. K. EDWARDS ASSOCIATES proposes to plug and abandon this well according

to the attached procedure.

COMMISSION APPROVED IT ANY	NMOCO	MOTEICTMANGOED	
Approved by	Title	1:0V 2×4 1995	
(This space for Federal or State office use)		APPHOVED	
Signed faul C. Though	Tide Paul C. Thompso	on - Agent 11/1/9.	
I hereby correcty that the foregoing is true and correct			

J. K. EDWARDS ASSOCIATES, INC. CHACO PLANT #36 1450'FNL & 1450'FWL, SECTION 36, T26N, R12W San Juan County, New Mexico

P & A PROCEDURE

- 1. MOL and RU. Hold safety meeting.
- 2. ND wellhead. Pull and lay down 36 joints of 1-1/4" tubing.
- 3. Pump plug #1 (35 sacks 42 cuft) down the 2-7/8" tubing.
- 4. Cut off wellhead. Fill 2-7/8" and 5-1/2" x 2-7/8" annulus with cement if necessary.
- 5. Restore location to BLM stipulations.

WALSH ENGINEERING & PRODUCTION CORP.

J.K. Edwards Chaco #36

Sec 36 T26N R12W

Status of well prior to P&A operations

