

F. Loc. 1070° S; 1000° W Elev. 6478 DR 6/5/54 Spd. 7/2/54 Comp. 2164 TD 2164 PB 2158
 Casing 8-5/8 @ 178 W 100 Sx. Int. @ W Sx. Pr. 5 1/2 @ 2114 W 75 Sx. T. 1 1/4 @ 2158
 Csg. Perf. Prod. Stim. SOF 2114-2164 w/2000 GO, 1200# and

LP. 589 3006 MCF/D After 3 Hrs. Sic. P. 461 PSI After 8 Days GOR Grav. 1st Del. 1-19-56 36 EP 546

TOPS		NITD	X	Well Log	TEST	DATA					
Kirland		C-102		Plat	Schd.	PC	Q	PW	PD	D	AIL
Fruitland		C-103		Electric Log							
Pictured Cliffs	2109	C-104	✓✓	C-110 11/23/55	*	No Test					
Cliff House		3-5-56			3/1/56	428	59	231	214	62	#229
Menefee		Remarks * No Meter Run Installed Disconnected From SOG 1-3-56 DITR 3-13-56 DFA 1-22-56 DATR 9-26-56 DAC 10-1-56			8/15/56	431	44	222	216	45	#1391
Point Lookout											
Mancos											
Tocito											
Dakota											
Morrison											
Entrada											
✓ PCD	4369									135	

W Kutz PC San Juan S 33 T 27N R 10W U M Oper. Stanolind Lse. Huerfano No. 22

Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	Oct.	Nov.	Dec.
U	M	Oper.	KPRC							
						Loc	Huerfano	No. 22		

33-27-10