Form 9-881 a (Feb. 1951)

(SUBMIT IN TRIPLICATE)

0 11

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4. Form Approved.

Land Office 1811 to Fe

Lease No. 047017+A

T-28-N.R-11-W.N.M.P.M. San Juan County, New Mexico.

SUNDRY NOTICES AND	D REPORTS ON WELLS
	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO PULL OR ALTER CONTINUES.	
INTERES AP INTENT TO RE-COMPLETE	* 611
(INDICATE ABOVE BY CHECK MARK NA	TURE OF REPORT, NOTICE, OR OTHER DATA)
-	March 11 , 19 63
Well No. 17 is located 990 ft. from	${N \atop S}$ line and 1650ft. from ${K \atop W}$ line of sec. 13.
NE/4.NV/4 Sec.13 T-28-N (B)	ange) (Meridian)
(K Sec. and Sec. No.) Dilcher Zitts (County or S	
The elevation of the derrick floor above sea leve	l is 5810ft. S OF WORK MAR 1 4 1963 OIL COM. COM.
DETAIL	, weights, and lengths of proposed casings; indicate mudding jobs, coment- er important proposed work)
(State names of and expected depths to objective sands; show sizes, ing points, and all oth	er important proposed work)
Me blobone co.	
1800 feet. Squeeze oil Open 100 sacks regular cement. (ron Cement Retainer at approximately hole from 1872 feet to 1982 feet w/ Pictured Cliffs Zone)
full bore packer and actures	shots/ft. from 1648 to 1688 feet.Run w/500 gallons sold and test for pro-
eroduction if natural test w	fraced in an effort to stimulate varrants.
[() \\ I understand that this plan of work must receive approval in \(\)	writing by the Geological Survey before operations may be commenced.
Company Southern Union Produ	etion Company
Address Post Office Box 808	Will D Woland &.
Farmington,	Gilbert D. Noland, Jr.
Hew Mexico	Title Drilling Superintendent

DETAILS OF WORK Continued

4. If Fruitland Zone is non-productive the Fruitland perfs. vill be cemented off and the 5 1/2" casing pulled from hole and the vell vill be permanently plugged and abandoned.