

F. Loc. 990/N; 840/E Elev. 5512 GL Spd. 425/56 Comp. 5/12/56 TD 1539 PB
 Casing S. 8 3/8 @ 102 W Sx. Int. @ W Sx. Pr. 4 1/2 @ 149 W 250 Sx. T. - 1 @ 1535
 Csg. Perf. Prod. Stim. SDF 1520-41 w/14000 W, 15000 T
 I.P. 400 NOF 8070 MCF/D After 3 Hrs. SICP 376 PSI After Days GOR Grav. 1st Del. 9/15/56

TOPS		NITD	X	Well Log	✓	TEST DATA						
Kirtland		C-102	✓	Plat	X	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland		C-103	✓	Electric Log	✓	1-7-56	355	151	212	178	172	A1591
Pictured Cliffs	1517	C-104	✓	C-110	✓	7/2/57	515	132	221	157	184	
Cliff House		116		C-122	✓	1/2-58	277					
Menefee		Ditr 11-21-56		Dfa		7-2-59	272	25	220	132	20	XM
Point Lookout		Datr		Dac		6-6-60	282	25	220	141	34	
Mancos		NIT - Repair well Remarks 8-29-79 NIT - PFA 12-16-82 disconnected 11-24-82 2-18-65 11/29/57 plug PC 1575-1465' 778945 + perf. Form. Sand 65 1/2 day 57' 11-2-12 160 T. A. Dugan Redfern Dev. Former Op. Redfern-Markham Prev. Redfern & Herd										
Tocito												
Dakota												
Morrison												
Entrada												

P
 o
 i Ful-Kutz PC Co. SJ s 16 T 28N R 11W UA Over. Dugan Prod. Corp. Redfern No. 1