Form 3160-5

UNITED STATES

FORM APPROVED

Budget B	ureau No.	1004	1-0135
Expires:	Septembe	er 30,	1990

(December 1989) DEPARTMEN' OF THE INTERIOR BUREAU OF LAND MANAGEMENT		Expires: September 30, 1990	
SUNDRY NOTICES A	ND REPORTS ON WELLS	5. Lease Designation and Serial No. SF-078904	
Do not use this form for proposals to drill of Use "APPLICATION FOR	PERMIT" for such proposals		
SUBMIT IN	N TRIPLICATE 070 FACT	7. If Unit or CA, Agreement Designation	
1. Type of Well OIL WELL GAS WELL OTHE	ER	8. Well Name and No.	
2. Name of Operator		Gallegos Canyon Unit 291	
Amoco Production Company	Melissa Velasco	9. API Well No.	
3. Address and Telephone No.		30-045-23822	
P.O. Box 3092 Houston, TX 77253	(294) 266 2546	10. Field and Pool, or Exploratory Area	
		Basin Fruitland Coal	
4. Location of Well (Footage, Sec., T., R., M., or Survey)	Description)	11. County or Parish, State	
1850' FSL 1850' FEL Sec 23	T28N R12W	San Juan New Mexico	
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTIC	CE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent Notice of Intent	★ Abandonment	Change of Plans	
Subsequent Report Recompletion		☐ New Construction	
	Plugging Back	Non-Routine Fracturing	
Final Abandonment Notice	Casing Repair	Water Shut-Off	
	☐ Altering Casing ☐ Other ☐ BLM Letter 9	Conversion to Injection	
	/10/1999		
	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		
 Describe Proposed or Completed Operations. (Clear work. If well is directionally drilled, give subsurface 	ly state all pertinent details, and give pertinent date locations and measured and true vertical depths	ates, including estimated date of starting any proposed for all markers and zones pertinent to this work.)*	
Amoco Production Company request	permission to plug and abandon the	subject well as per the attached well work	



Signed Permitting Staff Assistant	Date _	03/20/00
(This space for Federal or State office use) Approved by	D .	APR - 5 2000
Conditions of approval, if any:	Date _	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

SJOET Well Work Procedure

Well:

GCU 291

Version:

#1

Date:

March 15, 2000

Budget:

DRA **PXA**

Repair Type: SAP Project #:

X7-000FY

Objectives:

1. To PXA the entire well.

Pertinent Information:

Location:

J23 T28N-R12W, 1850 FSL, 1830 FEL

Horizon:

FC

County:

San Juan

API #:

3004523822 Allen Kutch

State:

New Mexico

Engr: Phone:

W (281) 366-7955

Lease:

SF-078904

Well Flac: Lease Flac:

886588 190715

Economic Information:

APC WI:

51.8% (PC)

100% (FC)

Estimated Cost:

\$7,500

Formation Tops: (Estimated formation tops)

San Jose:

surface

Menefee:

Nacimento: Ojo Alamo:

Point Lookout:

371 477 Mancos Shale:

Kirtland Shale: Fruitland:

1296

Gallup:

Pictured Cliffs:

1579 1780 Graneros: Dakota: Morrison:

Lewis Shale: Chacra:

Cliff House:

Bradenhead Test Information:

Test Date:

Tubing:

Casing:

BH:

Time 5 min

BH

CSG

INT

CSG

10 min

15 min

Comments:

GCU 291

Original Completion: 1/80 Recompletion: 12/96

TD = 1.817' PBTD = 1.578'

Objective: PXA entire wellbore (including Pictured Cliffs and Fruitland Coal)

Page 2 of 2

- 1. Notify regulatory agencies (BLM, NMOCD, FIMO) 24 hours in advance of plugging activity. Contact BLM and indicate well is allotted (FIMO regulations effective April 1, 1997).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 4. TOH with 2 3/8" tubing, remove mud anchor. TIH with 2 3/8" tubing workstring and tag CIBP set at 1,578'. Spot cement plug from 1,578' to 1,246' (26 sacks). TOH to 527', spot cement plug from 527' to surface (41 sacks).
- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Contact FMC and ship surface equipment to yard or other location per instructions.
- 7. Provide workorder to Buddy Shaw for reclamation.
- 8. Rehabilitate location according to BLM or State requirements.

GCU 291 (FC)

J23 T28N-R12W, 1850 FSL, 1830 FEL API 3004523822 SF-078904

Proposed PXA Wellbore Schematic

