State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	Sundry Notices and	Reports on Well	s
		API	# (assigned by OCD) 30-045-20681
1. Type of Well GAS		5.	Lease Number Fee
		6.	State Oil&Gas Lease
2. Name of Operator		7.	Lease Name/Unit Name
MERIDIAN OIL		8.	Lackey Well No.
3. Address & Phone No. of Opera			3
PO Box 4289, Farmington, NM	87499 (505) 326-9700	9.	Pool Name or Wildcat Aztec Pictured Cliff
4. Location of Well, Footage, St 1000'FSL, 1550'FEL, Sec.19,	ec., T, R, M T-29-N, R-9-W, NMPM, Sa		Elevation:
Type of Submission	Type of Ac	tion	
X Notice of Intent	Abandonment _ Recompletion	Change of Pl New Construc	
Subsequent Report	Plugging Back X Casing Repair	Non-RoutineWater Shut o	
Final Abandonment	Altering CasingOther -		
13. Describe Proposed or Comp It is intended to repair attached procedure		ct well accordi	ng to the
			ti e ti i i i i i i i i i i i i i i i i
			ECEIVED
		0	
	(ROS3) Regulatory		
(This space for State Use	2000 QEPUTY OIL & GAS INSPE	CTOR. DIST+#3FEB	1 6 1995

PERTINENT DATA SHEET

WELLNAME:					i				
WELLIAMINE.	Lackey #3				DP NUMBER: PROP. NUMBER:		52373A 072251801		
WELL TYPE:	Aztec Pictured Cliff	s			ELEVATION:	GL: KB:	5634' 5645'		
LOCATION:	SE Sec. 19, T29N,				INITIAL POTENTIAL:	AOF	2,931	MCF/D	
	San Juan County, New Mexico			SICP:	June, 1985	265	PSIG		
OWNERSHIP:	GWI: NRI:	52.471482% 43.813687%			DRILLING:		SPUD DATE: COMPLETED: TOTAL DEPTH: PBTD: COTD:	: :	07-31-70 08-31-70 2165' 2155' 2155'
CASING RECORD:									
HOLE SIZE	SIZE	WEIGHT	GRADE	<u>DEPTH</u>	EQUIP.		CEMENT	_	TOC
12-1/4"	8-5/8"	24.0#	KS	235'	•	180 sx			surface
6-3/4"	2-7/8"	6. 4#	JS-NU	2165		215 sx			893' (75%
Tubing	1-1/4"	2.3#	J- 55	2041'					
	Ran 2 jts (ta	ilpipe), Schlumi	oerger Mode	el AD-1 Pack	ter, 60 jts 1-1/4", 2.3#, J-55	, 10rd, tbg set	@ 2165'.		
FORMATION TOPS:	Ran 2 jts (ta Ojo Alamo Kirtland Fruitland Pictured Cliffs	ilpipe), Schlumt	880' 1035' 1755' 2018'	el AD-1 Pack	ter, 60 jts 1-1/4", 2.3#, J-55	, 10rd. tbg set o	@ 2165'.		
FORMATION TOPS:	Oje Alamo Kirtland Fruitland	ilpipe), Schluml	880' 1035' 1755'	el AD-1 Pack	er, 60 jts 1-1/4", 2.3#, J-55	, 10rd, tbg set	@ 2165'.		
	Ojo Alamo Kirtland Fruitland Pictured Cliffs		880' 1035' 1755' 2018'		ter, 60 jts 1-1/4", 2.3#, J-55	, 10rd. tbg set	@ 2165'.		
LOGGING:	Ojo Alamo Kirtland Fruitland Pictured Cliffs IES, FDC-GR	- 42', w/32 SPZ	880' 1035' 1755' 2018'	oles	ter, 60 jts 1-1/4", 2.3#, J-55		@ 2165'.		
LOGGING: PERFORATIONS: STIMULATION:	Ojo Alamo Kirtland Fruitland Pictured Cliffs IES, FDC-GR 2006' - 14', 2026' Fraced w/26,000#	- 42', w/32 SPZ 10/20 sand, 28	880' 1035' 1755' 2018' Total 64 H	oles tr., dropped 1 lure. Ran 62		650 gai. wtr.			
LOGGING: PERFORATIONS: STIMULATION:	Ojo Alamo Kirtland Fruitland Pictured Cliffs IES, FDC-GR 2006' - 14', 2026' Fraced w/26,000# June 1990: Emerg	- 42', w/32 SPZ 10/20 sand, 28 gency WO. Isola	880' 1035' 1755' 2018' Total 64 H	oles tr., dropped 1 lure. Ran 62	I set of 32 balls, flushed w/6	550 gal. wtr. 10rd, tbg and N		<u>ОіІ</u> О ЬЫ/П	

Lackey #3 Aztec Pictured Cliffs SE Section 19, T-29-N, R-9-W Recommended Casing Repair Procedure

- 1. Comply with all NMOCD, BLM and Meridian safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig.
- MOL and RU workover rig. Blow well down. NU 7-1/16" 3000 psi (6" 900 series) BOP with stripping head. Test and record operation of BOP rams. Kill well with 1% KCL water only if necessary.
- 3. TOH with 1-1/4" IJ, 2.3#, J-55 tbg (62 jts @ 2041') and Schlumberger Model AD-1 packer (1973') (To release pkr go down, then turn right. Repeat if necessary. May need to push pkr to perfs to equalize). Visually inspect tbg for corrosion. TIH with 2-7/8" casing scraper or gauge ring to PBTD at 2155' on 1-13/16" workstring. TOH.
- 4. TIH with 2-7/8" RBP and 2-7/8" retrievable packer on 1-13/16" workstring and set RBP at approx. 1906' (100' above top of PC perf). Pressure test RBP to 750 psig. Spot 10' of sand on top of RBP. Isolate casing failure and design squeeze cement job as appropriate. Establish a rate into hole with water and attempt to circulate to surface. Make sure bradenhead valve is open and a line is laid to the pit. If casing failure is shallow (1000' or less), bullhead cement down 2-7/8" casing and displace with newspaper wiper plug. If not, set 2-7/8" packer 600' above hole and establish a rate into hole with water. Establish 500 psig on backside. Make sure bradenhead valve is open. Mix and pump cement. Maximum pressure is 750 psig. If cement is circulated to surface, shut in bradenhead valve and squeeze. Displace cement 2 bbls below packer prior to attempting hesitation squeeze. Once squeezed, pull up hole, reverse circulate, and reapply pressure. Hold pressure for 4 hrs. and check for flowback. TOH with packer.
- 5. WOC 12 hrs. Clean out to below squeeze with 2-1/4" mill or bit. Pressure test to 750 psig. Re-squeeze as necessary.
- 6. TIH with 2-7/8" casing scraper to below squeeze. TOH. TIH with retrieving tool on 1-13/16" workstring blowing down with gas or air. Retrieve RBP and TOH.
- 7. TIH with 1-1/4" tubing with a seating nipple one jt off bottom and CO to PBTD at 2155'. Take and record gauges.
- 8. Land tbg near bottom perforation at 2042'. ND BOP and NU wellhead. Pump off expendable check valve and record final gauges. Return well to production.

Recommended: XOSTANJA

Approved: _____

Lackey #3

CURRENTAztec Pictured Cliffs

1000'FSL, 1550' FEL

SE Section 19, T-29-N, R-09-W, San Juan County, NM

