(N	m 3160-5 evember 1983) omerly 9-331)	UNITED STAT EPARTMENT OF THE BUREAU OF LAND MAN	INTERIOR	SUBMIT IN TRIPLICAT (Other instructions on verse side)	Budget Burea Expires Augu 5. LEASE DESIGNATION NM-03877	u No. 1004-0135	
- T- }	SUNDR'	Y NOTICES AND REI	PORTS ON	WELLS to a different reservoir.	G. IF INDIAN, ALLOTT	SHAN BEIST SO SEE	
I.					7. ONIT AGREEMENT	7. OHIT AGREEMENT NAME	
2.	NAME OF OPERATOR	8. PARM OR LEAGE W.	8. PARM OR LEASE WAME				
_	Mer	,	Duff				
3.	ADDRESS OF OPERATOR	9. WELL NO.	l				
	Pos	2 .	2 .				
4.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650'S 1090'W				10. FIELD AND POOL,	10. FIELS AND POOL, OR WILDCAT	
					Crouch Mesa Verde		
					11. SSC., T., R., M., OS SURVET OR ARI	11. SEC., T., B., M., OR BLE. AND SURVEY OR AREA	
					Sec.5, T-29-N, R-11-W		
14	PRRMIT NO.	15. SLEVATIONS (Sho	= whether no se	TR. etc.)	N.M.P.M.		
14.	FERRIL NO.	19. 5227216.15 (525	5820 '			1	
_				· · · · · · · · · · · · · · · · · · ·	San Juan	NM	
16.	C	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data					
	NOTICE	NOTICE OF INTENTION TO: SUBSECT					
	TEST WATER SEUT-OFF	PULL OR ALTER CASING		WATER SEUT-OFF	REPAIRING	ware.	
	PRACTURE TREAT	MULTIPLE COMPLETE		PRACTURE TREATMENT	ALTERING	_	
	SHOOT OR ACIDIES	ABANDON*	$ \nabla $	SHOOTING OR ACIDISING	ABANDONM	i [
	REPAIR WELL	CHANGE PLANS		(Other)			
	(Other)	(Nots: Report rest Completion or Reco			its of multiple completion on Well upletion Report and Log form.)		
17.	nent to this work)	PLETED OPERATIONS (Clearly state is directionally drilled, give sub				·	
We plan to abandon this well on or about September 30, 1987 with the following procedure: 1. Circulate the well with 9 ppg mud. 2. Install BOP. 3. Spot a 10 sx plug below the retainer @ 3660'.						tn tne	
	-						
 Spot a 20 sx plug on top of the retainer. Tag plug after WOC (3450'). 							
 ۸		PC & Fruitlan	ıd				
*	Formati		-				
	7. Perfora	pot 30 sx ins	side csg				
	to cove		. /D/s.				
	8. Perforate @ 379' & circulate cement to surface				e. <i>[Q] _{[S}</i>		
	9. Cut off	wellhead & inst	all Dry F	Hole Marker.			
					OIT COV	51987	
					OIST.	Dis	

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT CALLER SERVICE 4104 FARMINGTON, NEW MEXICO 87499

Attachement of Notice of

Intention to Abandon

Re: Permanent Abandonment

Well: 2 Duff

CONDITIONS OF APPROVAL

- Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. The Farmington Office, telephone (505) 325-4572, is to be notified in sufficient time for a representative to witness all plugging operations.
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

acld plug as follows

plug 2753' -2653' Chacra

plug 1728' -1628' Fruitland

Office Hours: 7:45 A.M. to 4:30 P.M.