Form 9- talay 1		Form approvement of the state o	AND SERIAL NO.	
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME	
1.	L GAR X OTHER	7. UNIT AGREEMENT N	AME	
2. NAM	NAME OF OPERATOR		S. FARM OR LEASE NAME	
La	Ladd Petroleum Corporation		Aztec	
	ADDRESS OF OPERATOR		9. WELL NO.	
	O Denver Club Bldg., Denver, CO 80202	2-35		
ુ અલ્	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT	
	0' FSL & 990' FEL - Sec. 35-T30N-R14W-NMPM	Basin Dakota		
05	0 131 % 990 FEL - Sec. 35-130N-R14W-NAPM	11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA		
14. PEB	MIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	35-30N-14W-N		
	5527 DF	12. COUNTY OR PARISI		
		San Juan	New Mexico	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or C	Other Data		
	NOTICE OF INTENTION TO:	ENT REPORT OF:		
TE	ST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING	WELL	
FR.	ACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING C	ASING	
вн	OOT OB ACIDIZE ABANDON. X SHOOTING OR ACIDIZING	ABANDONME	NT*	
	PAIR WELL CHANGE PLANS X (Other)	of multiple completion on Well		
	Completion or Recomple	etion Report and Log fo	rm.)	
	RIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, roposed work. If well is directionally drilled, give subsurface locations and measured and true vertica ent to this work.)	including estimated da l depths for all marker	te of starting any	
Cha in	Pull tubing from 5748'. Plug#3 200' plug across Messavered Cut off and pull casing (+1000').	ug back and results 4929	ecomplete 5-4825 La	
1)	Pull tubing from 5748'. Plug#3 200 plug across Masswerd	le 2850'-2650 casing	. Perfand	
2)	Cut off and pull casing (+1000').			
3)	Set cement plugs:			
	(a) 20 sx across perfs 5748-5772' in 4½" casing. (b) 10 sx across top of cut off 4½" casing.	•		
	(c) 25 sx in top of 9-5/8" surface casing. Plug## 250 plug across Picture	4		
4.		of Cliffe Tre	itland coal	
4)	Leave mud between plugs. and casing stub 1200-95 perf + spluere cement	Q. Jacons	eccount - 10	
5)	Weld plate and install marker. Plug \$5 100' plug across		300'-	
6)	·		1000	
0)	Comply with surface restoration stipulations, as contained regarding subject well (dated 1/25/80).	in HIM Tetter OIL CON. DIST.	1930 GS COM. 3	
	reby certify that the forgeoing is true and correct	_		

Division Engineer

3/18/80

(This space for Federal or State office use

TITLE

APPROVED

of Frank

*See Instructions on Reverse Side

DISTRICT OIL & GAS SUPERVISOR