5. LEASE

14-00-0001-62

# UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN ALLOTTEE OR TRIBE NAME	
·	Navajo - <u>Uto t</u> n.	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
	Horseshoe Gallup Unit	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	
	Horseshoe Gallup Unit	
1. oil gas other Injection	9. WELL NO.	
	135	
2. NAME OF OPERATOR ARCO Oil and Gas Co., a		
Div. of Atlantic Richfield Company	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR 707 - 17th Street,	Horseshoe Gallup	
P.O. Box 5540, Denver, Colo. 80217	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	
below.)	Sec. 5-30N-16W	
AT SURFACE: Unit L,2310'FSL & 990'FWL, Sec. 5	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL:	San Juan New Mexico	
AT TOTAL DEPTH:	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	None	
REPORT. OR OTHER DATA		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5317' GR	
	:	
1231 476124 3601-361	$\bar{r}$	
FRACTURE TREAT		
REPAIR WELL	(NOTE: Report results of multiple completion or zone	
PULL OR ALTER CASING	change on Form 9-330.)	
MULTIPLE COMPLETE	•	
CHANGE ZONES		
ABANDON*		
(other) X - Set Cement Plug		
	<u> </u>	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine	lirectionally drilled, give subsurface locations and	
ARCO hereby asks permission to set a cerinterval (1026-1163' OA ) in the subject with the requirements as set forth in a 1981, and a subsequent letter of April of New Mexico, Energy and Minerals Depa Division (copies attached.)	t well. This is in compliance memorandum dated September 30, 26, 1982, both from the State	
Attached is the procedure for setting to	he cement plug.	
This Approval (1.1 to cross) 10-16-8		
Subsurface Safety Valve: Manu. and Type	Set @ Ft.	
18. I hereby certify that the foregoing is true and correct		
$04.1 \cdot 0$	C::n+ August 31 1002	
SIGNED TITLE DIST. Prod.	Supt.date August 31, 1982	
This space for Federal or State o	ffice use)	
A.AROVED		
APPROVED BY	DATE	
CONDITIONS OF APPROVACHE MANY		
0CT 1.7 1982		
MANUAMES F. C. See Instructions on Reverse	Side	

### HORSESHOE GALLUP UNIT INJECTION WELLS

### PLUGGING PROCEDURE

- 1. MIRU.
- 2. Release packer and pull tubing and packer out of hole.
- 3. RIH with tubing open-ended to 40' above the top perforation and pump sufficient cement to set a 100' plug inside the casing (Using light-weight cement).
- 4. POH, RD, and move off.



### STATE OF NEW MEXICO

### ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

BRUCE KING SOVERNOR ARRY KEHOE SECRETARY

April 26, 1982

POST OFFICE BOX 2088
STATE LAND OFFICE BUILDING
SANTA FE. NEW MEXICO 87501
(505) 827-2434

RECEIVED

APR 30 1982

ENGINEERING

Arco Oil & Gas Company P.O. Box 5540 Denver, Colorado 80217

ATTENTION: J. G. Bradshaw

RE: Exception to Rule 705-A for Injection Wells in the Horseshoe Gallup Unit, Federal Lease No. 14-08-0001-8200, San Juan County,

New Mexico.

#### Dear Sir:

Pursuant to your letter of February 18, 1982, requesting exception to Rule 705-A for fifty-seven (57) wells as listed on Table I, the Oil Conservation Division hereby denies both of your requests. You are hereby requested to take prompt action as outlined in the September 30, 1981, Memorandum. (Copy enclosed).

The Oil Conservation Division will not grant an exception to Rule 705-A if a well will not be placed in service within 6 months of the request. For future reference, supportive data for exception to Rule 705-A should include:

- 1. Proof of mechanical integrity, such as bradenhead tests, tracer logs, or other supportive tests or data.
- 2. All related OCD Division Order Numbers or Case Hearing Numbers.
- 3. A schematic of the present injection well including cement tops and quantities thereof.
- 4. Date each well was shut-in.

If you have any questions regarding this matter, please do not hesitate to contact me at (505) 827-2533.

Sincerely,

JOE D. RAMEY

Division Director

### TABLE I

Horeshoe Gallup Unit Federal Lease No. 14-08-001-8200 San Juan County, New Mexico.

### List of Wells

⊥.	NO.	26	b

2. No. 29 B

3. No. 103 A

4. No. 105 A

5. No. 113 A

6. No. 126 C

7. No. 130 C

8. No. 132 C

9. No. 135 C

10. No. 137 C

11. No. 139 C

12. No. 141 C

13. No. 143 D

14. No. 145 D

15. No. 148 D

16. No. 150 D

17. No. 152 D

18. No. 154 D

19. No. 156 D

20. No. 160 D

21. No. 215 D

22. No. 162 D

23. No. 164 D

24. No. 169

25. No. 171 D

26. No. 173 D

27. No. 175 D

28. No. 190

29. No. 182 D

30. No. 184 D

31. No. 186 🔾

32. No. 192

33. No. 194 D

34. No. 196

35. No. 201

36. No. 203

37. No. 205 D

38. No. 207 🗗

39. No. 213 📮

40. No. 217 D

41. No. 223 D

42. No. 225

43. No. 227 D

44. No. 229 D

45. No. 238 D

46. No. 240 D

47. No. 248 D

48. No. 250 D

49. No. 259 D

50. No. 261 C

51. No. 263 C

52. No. 269 C

53. No. 274 C

54. No. 275 C

55. No. 73 A

56. No. 199

-57. No. 211



SECRETARY

## ENEMBY AND IVITALEMALS DEFABLIVILIAL OIL CONSERVATION DIVISION

POST OFFICE BOX 20 STATE LAND OFFICE BL . SANTA FE, NEW MEXICO : (505) 827-2434

MEMORANDUM

TO: ALL NEW MEXICO INJECTION WELL OPERATORS

FROM: JOE D. RAMEY, DIRECTOR

SUBJECT: TEMPORARY ABANDONMENT OF INJECTION WELLS

Division Rule 705A provides in part that "no injection well may be temporarily abandoned for more than six months unless the injection interval has been isolated by use of cement or a bridge plug." The Division Director may delay the cement or bridge plug requirement upon a request by the operator and a showing that such well is mechanically sound, that there is a continuing need for the well, and that the well constitutes no threat to underground sources of drinking water.

Division survey programs have found several hundred injection wells which have not been used for at least six months and which do not have the requisite plugs. Based upon these surveys the Division will be moving to enforce Rule 705A in the near future.

Operators should review the status of their injection wells and within the next six months take one of the following actions relative to injection wells which have been shut in for six months or longer:

- (1) Return the well to active operation.
- (2) Plug and abandon the well or place a <u>cement</u> or bridge plug above the injection interval.
- (3) File a workover or plugging plan and schedule with the appropriate Division district office.
- (4) File a request for exception to Rule 705A with the Division Director in Santa Fe.

September 30, 1981 fd/