Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED						
Budget Bureau No	. 1004-0135					
Expires: March	31 1993					

5.	Lease	Designa	tion :	hand	Serial	Nο

	LAND MANAGEMENT	5. Lease Designation and Serial No.	
SUNDRY NOTICES A	ND REPORTS ON WELLS	SF-079004	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		6. If Indian, Allottee or Tribe Name	
	PERMIT - * for such proposals		
		7. If Unit or CA, Agreement Designation	
SUBMIT	IN TRIPLICATE		
1. Type of Well Oil Y Gas		San Juan 32-8 Unit	
Well Other		Well Name and No.	
2. Name of Operator Phillips Petroleum Company		SJ 32-8 Unit #21	
3. Address and Telephone No.	6 to Contract to	API Well No.	
5525 Highway 64, NBU 3004, Farming	ton, NM 87401 505-599-3454	30-045-10781 10. Field and Pool, or exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey D		10. Field and Foot, of exploratory Area	
Unit A, 960' FNL & 1146' FEL		Blanoc Mesaverde	
Section 15, T31N, R8W	11. County or Parish, State		
		San Juan, NM	
12. CHECK APPROPRIATE BOX(s	s) TO INDICATE NATURE OF NOTICE, REPORT,	OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
X Notice of Intent	Abandonment		
LEE FORCE OF MICH	Recompletion	Change of Plans New Construction	
Subsequent Report	Plugging Back		
	Casing Repair	Non-Routine Fracturing Water Shut-Off	
Final Abandonment Notice	Altering Casing		
	X Other Add pay and stimulate	Conversion to Injection Dispose Water	
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true vert	l pertinent details, and give pertinent dates, including estimated date of starti tical depths for all markers and zones pertinent to this work.)*	ng any proposed work. If well is directionally drill	
MIRU. ND WH & NU BOPs. POOH w/pro PT casing. If casing fails test -	duciton tubing. Isolate existing Mesaverde isolate failure. Remediate with cement.	perfs with bridge plug.	
If well recents indicate no coment	across the Lewis Shale interval, it may be n		
bond log (CBL). Shoot squeeze hole the Lewis Shale.	es in casing and pump sufficient volumes of c	ement to cover and isolate	
bond log (CBL). Shoot squeeze hole the Lewis Shale.	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are	ement to cover and isolate	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S plug and run production tubing. Flo	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are	ement to cover and isolate run). Retrieve bridge	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are	ement to cover and isolate	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S plug and run production tubing. Flo	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are	run). Retrieve bridge	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S plug and run production tubing. Flo	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are	ement to cover and isolate run). Retrieve bridge	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S plug and run production tubing. Flo	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are	run). Retrieve bridge	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S plug and run production tubing. Flo	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are	run). Retrieve bridge	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S plug and run production tubing. Fl. A workover pit may be required.	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are	run). Retrieve bridge	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S plug and run production tubing. Flow A workover pit may be required.	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are	run). Retrieve bridge	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S plug and run production tubing. Flow A workover pit may be required. 4. I hereby contribute the foregoing in the old correct Signed (This space for Federal or State office use)	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are ow test the Lewis Shale.	ement to cover and isolate run). Retrieve bridge 99 JN 22 Pl Date 1/22/99	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S plug and run production tubing. Flow A workover pit may be required. A workover pit may be required. (This space for Federal or State office use) Approved by	es in casing and pump sufficient volumes of controls hale (perfs to be determined after logs are ow test the Lewis Shale.	ement to cover and isolate run). Retrieve bridge 070 F3 22 P1 Date 1/28/99	
bond log (CBL). Shoot squeeze hole the Lewis Shale. Perforate and stimulate the Lewis S plug and run production tubing. Flow A workover pit may be required. 14. I hereby control that the foregoing in true and correct Signed Chris space for Federal or State office use)	tide Regulatory Assistant	ement to cover and isolate run). Retrieve bridge 99 JH 22 PH Date 1/22/99	



* See Instruction on Reverse Side