Form 9-331 (May 1963)

UNITED STATES SUBMIT IN TRIPLICATE* Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424.

GEOLOGICAL SURVEY

l		A . 1	/	
1	C11.	αθααα).	_	

	S	F	080	0004			_		
6.	IF	IN	DIAN,	ALLOT.	ree	OR	TRIBE	NAME	

SUNDRY	NOTICES	AND	DEDORTS	ON	WELLS	
VIINIIKY	NULLEY	AINU	ベビアくノバコン	UIN.	VVELLO	

REPAIR WILL Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data Subsequent Teals of Indicate Teals of Motice of Intervior of Actines of Actines of Actines of Motice of Intervior of Actines of Actine	De not use this form for	proposals to drill or to deepen or plug b PLICATION FOR PERMIT—" for such pr	ack to a different reservoir.	İ				
Tenneco Oil Company P. O. Box 1714 - Durango, Colorado P. O. Box 1714 - Durango, Colorado P. O. Box 1714 - Durango, Colorado P. O. Box 1715 - Durango, Colorado P. O. Box 1715 - Durango, Colorado P. O. Box 1715 - Durango, Colorado P. O. Box 1716 - Durango, Colorado P. D. Box			-	7. UNIT AGREEMENT NA	M E			
Tenneco Oil Company Address of Oferator P. O. Box 1714 - Durango, Colorado Discribio for Mill. (Report location clearly and in accordance with any State requirements.* See also space IT below.) At surface 855' FSL, 1060' FWL Unit M 15. ELEVATIONS (Show whether DF, RT, GR, etc.) Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL COLOR TO COMPLETE OFERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or completion or Report and Log form: Rig up rotary, Spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to Surface. Woc. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. :7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.		₹FR						
ADDRESS OF OTERATOR P. O. BOX 1714 - Durango, Colorado DICATION OF MELL (Report location clearly and in accordance with any State requirements.* See also space IT below.) At surface 855' FSL, 1060' FWL Unit M 15. BLEVATIONS (Show whether DF, RT, GR, etc.) Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL Other) COMPTETED OF COMPTETED OF SHATE CARING PRODUCED OR COMPTETED OF SHATE CARING COLORY OF PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL COLORY OR PARISH OCHER OF INTENTION TO: WATER SHUT-OFF PRACTURE TREATMENT SHOOT OR ACIDIZE COMPTETED OF SHATE ABANDON' OCHER PRODOSED OR COMPLETED OF SHATE CARING COLORY OF PRACTURE TREATMENT SHOOT OR ACIDIZE COMPTETED OF SHATE ABANDON' OCHER OF INTENTION SEED OF SHATE CARING OCHER) 7. DESCRIPE PRODOSED OR COMPLETED OF SHATE CARING COLORY OF PRACTURE TREATMENT SHOOT OR ACIDIZE COMPTETED OF SHATE ABANDON' OCHER OF INTENTION SEED OF SHATE CARING OCHER OF INTENTION SEED	. NAME OF OPERATOR			8. FARM OR LEASE NAM	í B			
D. O. BOX 1714 - Durango, Colorado Document Colorado December Decemb	Tenneco Oil Com	npany	· · · · · · · · · · · · · · · · · · ·					
NOTICE OF INTENDED AND PERMIT NO. 15. BLEVATIONS (Show whether DF, NT, GR, etc.) 12. COUNTY OR PARISHE 13. STATE SAN JUAN New Mexic				1 .				
Section 14. T-30-N. R-9. Section 14. T-30-N. R-9. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH: 13. STATE San Juan New Mexic 6. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE SHOOT OR ACIDIZE SHOOT OR AC	P. O. Box 1714	- Durango, Colorado	G1-1					
4. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 7. DESCRIPT PROPOSED OR COMPLETE DOPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D.: 7.7# 107d, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.	See also space 17 below.)	ition clearly and in accordance with any	State requirements,*		10. FIRED AND POUL, OR WINDCAL			
Section 14. T-30-N, R-9. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 7. DESCRIBE PROPOSED OR COMPLETE OF SHANDON'S REPAIR WELL (Other) 7. DESCRIBE PROPOSED OR COMPLETE OF STATEMENT (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sonce pertinent to this work.) Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WOC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 21.7# 107d, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.								
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) T. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 27.7# 1.Ord, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.	855' FSL, 1	LOGO'FWL Unit M		SURVEY OR AREA				
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) T. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 27.7# 1.Ord, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.				Section 14. T	-30-N. R-9-			
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPART WELL (Other) 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" O.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.	14. PERMIT NO.	15. ELEVATIONS (Show whether DF	, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE			
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" O.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.				San Juan	New Mexico			
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" O.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.	6. Char	L Appropriate Box To Indicate	lature of Notice, Report,	or Other Data	-			
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WOC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.		••						
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WOC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.		THE OF ALTERS CLEANED		Y REPAIRING W	WELL			
SHOOT OR ACIDIZE REPAIR WELL (Other) 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.		-		ALTERING CA	ASING			
REPAIR WELL (Other) (Other) (Other) (Other) (None: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.			1	ABANDONMEN	NT*			
(Other) (Nors: Report results of militiple completion on well Completion or Recompletion Report and Log form.) 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.			(Other)					
Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WOC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.	(Other)		Completion or Re	completion Report and Log for	rm.)			
Rig up rotary, spud 2-15-66. Drill to 141'. Ran 4 joints 8-5/8" 24# J-55 casing set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WOC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 7.7# lord, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.	17. DESCRIBE PROPOSED OR COMPLET	ED OPERATIONS (Clearly state all pertinen directionally drilled, give subsurface loca	t details, and give pertinent of tions and measured and true v	lates, including estimated date ertical depths for all markers	e of starting any s and zones perti-			
set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.	nent to this work.) *	•	u.					
set at 140'. Cemented with 100 sacks cement. Circulated cement to surface. WCC. Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig.				0 = /011 0) 4 = ==	and no			
Drilled cement and drilled to T.D. 3033'. Logged. Ran 98 joints 3-1/2" 0.D. 7.7# 10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig. RECEIVED	Rig up rotary, sp	oud 2-15-66. Drill to 1	41. Ran 4 Joints	coment to surface	caerus			
10rd, J-55 casing set at 3032'. Cemented with 440 sacks followed by 50 sacks cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig. RECEIVED	set at 140'. Cen	mented with 100 sacks ce	ment. Circulated	Cement to surface	n :7.7#			
cement. Top cement by temperature survey is 925. Released rig 2-20-66. Now waiting on completion rig. RECEIVED	Drilled cement an	ad drilled to T.D. 3033.	. Logged. Ran 90	followed by 50 car	Þ•:≃(• π			
waiting on completion rig. RECEIVED	Tora, J-55 casing	set at 3032. Cemente	u wim 440 backs i	of rig 2-20-66. M	UM TO			
RECEIVED								
RECEIVED RECEIVED	war crug ou compre	stion its.	_		•			
RECEIVED RECEIVED								
OFFEVED RECEIVED			<i></i>					
OFFILIVED 10cc		SCII N		RECEIVED	5			
/Q[\L\\L\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		(CL+I/I	10		7			
		/QT1,L14"	LD \	MAR 2 1966				

SIGNED Harold C. Nichols	TITLE _	Senior	Production	Clerk	DATE	2-28-66
(This space for Federal or State office use)					••	
APPROVED BY	TITLE _			·	DATE	

Distribution:

5 - USGS
1 - Continental

*See Instructions on Reverse Side

1 - File