OIL CONSERVATION COMMISSION

1000 RID BRAZUS ROAD AZTEC, NEW MEXICO ION Comment of .

October 8, 1964

Southwest Production Company 3108 Southland Center Dallas, Texas

Gentlemen!

Bradenhead test which was conducted on your #1 Newberry Federal well located in Unit M, Section 17-31N-12W indicates production casing failure in this well.

You are, therefore, directed to take immediate remedial action to repair the casing in this well. Prior to commencement of operations, Form C=102 indicating your plan of action should be filed in triplicate in this office.

Yours very truly

Emery C. Arnold Supervisor, District #3

BCA : ks

cc: U.S.G.S., Farmington, N.M.
OCC, Santa Fe, N.H.
Fred Crum, Astec, N.H.

## OIL CONSERVATION COMMISSION 1000 RID BRAZOS ROAD

AZTEC, NEW MEXICO

Galober B, 1964

Southwest Fraduceian Company 3108 Southland Senter Sallas, Pexas

Genilenens

braceahead lest which was conducted on your 41 Neubarry Yederal well located in thit My dection 17-314-124 indicates production casing failure in this well.

iou ara, therefore, directed to take immediate remedial ontion to regain the casing in this well. Infor to commencement if operations, Form U-102 indicating your plan of notion should be filed in triplicate in this office.

นุริมาร์ ยุราร ธานารู

Phery C. Arnold Supervisor, Listrict #3

BUA : KE

ect H.A.C.S., Marnington, M.m. 2005, Santa Fe, A.M. Free Grun, Latec, N.a.