#### UNITED STATES

# DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



Sundry Notices and Reports on Wells Lease Number NM-0607 UN tradiminations, tail If Indian, All. or 1. Type of Well Tribe Name GAS 7. Unit Agreement Name 2. Name of Operator MERIDIAN OIL 8. Well Name & Number Atlantic C #2A 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 9. API Well No. 30-045-22786 10. Field and Pool 4. Location of Well, Footage, Sec., T, R, M Blanco Mesaverde 920'FSL, 1930'FEL, Sec.35, T-31-N, R-10-W, NMPM 11. County and State San Juan Co, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Action Type of Submission \_\_\_\_ Abandonment \_\_\_ Change of Plans \_X\_ Notice of Intent New Construction Recompletion Non-Routine Fracturing \_\_\_ Plugging Back Subsequent Report Casing Repair Water Shut off
Altering Casing Conversion to Injection Final Abandonment \_X\_ Other - Tubing repair Describe Proposed or Completed Operations 13. It is intended to workover and repair the tubing for the subject well according to the attached procedure and wellbore diagram. OIL COM. DIV. DETL 3 I hereby certify that the foregoing is true and correct. (LWD5) Title Regulatory Affairs Date 6/23/95 (This space for Federal or State Office use) A.P. PROVED Title APPROVED BY CONDITION OF APPROVAL, if any:

#### **WORKOVER PROCEDURE - TUBING REPAIR**

Atlantic C 2A DPNO 48449A Blanco Mesaverde SE, Section 35, T31N, R10W San Juan County, New Mexico

- 1. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM, and MOI safety regulations.
- 2. MOL and RU. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 1% KCl water as necessary. ND wellhead and NU BOP. Test BOP.
- 3. POH 2-3/8" tbg (193 jts). Inspect tubing and replace all bad joints. (Note any buildup of scale, and notify Operations Engineer. If tubing is excessively scaled, acid wash may be run in perforations.) LD bull plug and perforated pup joint. PU and RIH with 3-7/8" bit and 4-1/2" 10.5# casing scraper to PBTD (5950'). POH.
- 4. PU 4-1/2" fullbore packer and RIH. Set @ 4613'. Pressure test casing to 1000#. (If casing does not test, notify Operations Engineer. Isolate failure and repair.) Release packer and POH.
- 5. RIH with open-ended 2-3/8" 4.7# tbg. Land @ 5853'.

6.	ND BOP, NU	wellhead.	rig down,	move off	location,	and restore	location.
----	------------	-----------	-----------	----------	-----------	-------------	-----------

Recommended	Summer Engineering Intern
Approval:	
	Production Superintendent

Contacts:Operations EngineerLarry Dillon326-9714Summer Engineering InternElizabeth Thomas326-9582

PET

### **PERTINENT DATA SHEET**

6/22/95

99 Mcf/d  8 psig psig  DATE: 3/8/78  LETED: 5/4/78  DEPTH: 5969' PBTD: 5950'	072257200		PROPERTY NUMBER:					
8 psig psig  DATE: 3/8/78 LETED: 5/4/78 DEPTH: 5969' PBTD: 5950'  T TOC	6474'	GL: KB:	ELEVATION:			9	Blanco Mesaverdo	WELL TYPE:
psig  DATE: 3/8/78 LETED: 5/4/78 DEPTH: 5969' PBTD: 5950'	3.999		INITIAL POTENTIAL:			ow	920' FSL, 1930' F Sec.35, T31N, R1	LOCATION:
DEPTH: 5969' PBTD: 5950'  T TOC			INITIAL SICP: CURRENT SICP:			, New Mexico	San Juan County	
	SPUD DATE: COMPLETED: TOTAL DEPTH: PBTD:		DRILLING:			100.0000% 85.5000% 0.0000%	GWI: NRI: SJBT:	OWNERSHIP:
	<del></del>				<del></del> -			CASING RECORD:
Surf-cire	CEMENT		EQUIP.	DEPTH	GRADE	WEIGHT	SIZE	HOLE SIZE
	295 cf			218'	K-55	3 <b>6#</b>	9-5/ <b>8"</b>	13-3/4"
27 <b>25</b> ' (T	383 cf			3570'	K-55	20#	7-	8-3/ <b>4"</b>
	434 cf		Liner top @ 3421'	59 <b>69</b> '	K-55	10.5#	4-1/2"	6-1/4"
nipple 1 jt above total string 3'			Bull plug on bottom 5855' set @ 5866',	5 <b>866</b>	J-55	4.7#	2-3/8"	Tubing
		5040' 5470'	Menefee Point Lookout		1875' 1965' 2050' 3200' 3375' 4840'		Ojo Alamo Kirtland Fruitland Coal Pictured Cliffs Lewis Mesaverde	FORMATION TOPS:
						тѕ	IL-GR, CDL-GR,	LOGGING:
					Z	40-5359 w/1 SP	Upper perfs: 47 Middle perfs: 50 Lower perfs: 53	PERFORATIONS
			tr.	000 gal. wti	20/40 & 93.	aced w/49,000#	Upper perfs: Fr Middle perfs: Fr Lower perfs: Fr	STIMULATION:
							None	WORKOVER HISTORY:
	<u>Gas</u> 314 Mct/d	CTION:	DATE OF LAST PRODUC April, 1995			Oil 9.2 MMcf 0.5 b/d	<u>Gas</u> 2.2 Bcf 314 Mcf/d	PRODUCTION HISTORY: Cumulative as of 1995: Current:
		CTION:				9.2 MMcf	2.2 Bcf	

**EPNG** 

PIPELINE:

## ATLANTIC C 2A x2 2.720 CURRENT Blanco Mesaverde **DPNO 48449A** 920' FSL, 1930' FEL, SECTION 35, T31N, R10W SAN JUAN COUNTY, NEW MEXICO Und fortambelong the Today's Date: 6/20/95 13-3/4" Hole Spud: 3/8/78 Completed: 5/4/78 9-5/8" 36# K-55 csg set @ 218' Circ. cmt to surface Ojo Alamo @ 1875' Kirtland @1965' Fruitland @ 2050' TOC @ 2725' w/383 cf cmt (TS) Pictured Cliffs @ 3200' Lewis @ 3375' Top of Liner @ 3421' 8-3/4" Hole 7" 20# K-55 csg set @ 3570" TOC @ 2725' (TS) 2-3/8" 4.7# J-55 tbg set @ 5866" (Bull plug on bottom, 3 ft perf jt & seating nipple 1 jt above total string 5855' set @ 5866' seating nipple @ 5833'.) Upper perfs: 4713-5005' w/1 SPZ Mesa Verde @ 4840' Menefee @ 5040' Middle perfs: 5040-5359' w/1 SPZ Point Lookout @ 5470' Lower perfs: 5381-5853' w/1 SPZ 4-1/2" 10.5# K-55 Liner set @ 5969', cmt w/434 cf to 3421' PBTD @ 5950'

TD @ 5969'