UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SF-079909 5. Lease Number SF-078389A
6. If Indian, All. or Tribe Name
San Juan 32-9 Unit 8. Well Name & Number San Juan 32-9 U 4A 9. API Well No. 10. Field and Pool Blanco Mesa Verde 11. County and State San Juan Co, NM
E, REPORT, OTHER DATA tion Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injectio
RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED
ffairs A Pare H & V (24)

WORKOVER PROCEDURE

SAN JUAN 32-9 UNIT # 4A Mesa Verde SE/4 Sec. 12, T31N, R10W San Juan Co., New Mexico

- 1. Strip location of production facilities. Test location rig anchors and repair if necessary. Prepare blow pit.
- MOL and RU workover rig. Set blowback tank and NU relief line to blowback tank.
- 3. Comply to all NMOCD. BLM, and MOI regulations. Conduct safety meeting for all personnel on location.
- 4. Blow well down to blowback tank. Kill well with 2% KCl water. ND christmas tree and NU BOP's. BOP's will be nippled up on a 11" 2000 x 7 1/16" 2000 Rector tubing spool.
- 5. PU on 2 3/8" production tubing and unseat tubing hanger. Freepoint tubing string, and backoff or chemical cut tubing. POOH laying down production tubing. PU fishing assembly and 2 3/8" workstring, and retrieve remaining production tubing.
- 6. Inspect (EMI, drift, and clean ends) production tubing on pipe rack during fishing operations.
- 7. PU 6 1/4" bit and clean out to liner top at 3590' with gas. TOH. PU 3 7/8" bit and clean out to PBTD of 6083' with gas. Blow well clean and obtain gauges. POOH laying down workstring.
- 8. Run MTT-Caliper casing inspection log in 7" casing from top of 4 1/2" liner to surface. Contact Operations Engineer (ext. 9714) three hours prior to running wireline tools.
- PU production tubing with an expendable check on bottom, and a new 'F' nipple (1.43" bore) one joint off bottom. Land tubing at ≅ 6000'.
- 10. ND BOP's and NU christmas tree. Drop ball and pump off expendable check.

11. Release rig.

Recommended:

Operations Engineer

Approval:

Drilling Superinte

WE CEINE

MAR 2 8 1994

Inspection: Wireline:

Frontier Inspection

Blue Jet

325-7806 325-5584

> 0]]L ((0)N. DIV. **DIST. 3**

Pertinent Data Sheet

San Juan 32-9 Unit # 4A Well Name:

DP Number: 69840

Well Type:

Mesa Verde

Elevation:

6574' GL 5727' KB

Location:

1670' FSL, 1090' FEL, Sec 12, T31N, R10W

San Juan Co., New Mexico

Ownership:

GWI: 42.9146%

Drilling:

Spud Date:

Jun. 10, 1978

NRI: 33.4126% Total Depth: PBTD:

61011 6083'

Casing and Tubing:

Hole Size 13 3/4" 8 3/4"

Size, Wt, & Grade 9 5/8", 36#, K55 7", 20#. K55

Depth 225' 3735' 3590'-6083'

6048'

Cement 190 sx 287 sx

TOC Surf 3300' - Temp

6 1/4"

4 1/2", 10.5#, K55 2 3/8", 4.7#, J55, EUE 320 sx

Rev out 10 bbl

Geology:

Field: Blanco Mesa Verde

Formation Tops:

Nacimiento Ojo Alamo

Kirtland

Surface 1847' 1902' 2990'

Pictured Cliffs 3382' Lewis

Fruitland

3530'

Mesa Verde Menefee

5215' 5315

Point Lookout 5655'

Logging:

GR-Induction 225' - 6100'; GR-Density 5100'-6100'

Perforations: Limited Entry, 5171'-5543' (Total of 16 shots), 5607'-6057' (Total of 24 shots).

Stimulation:

Fraced with 314.657 gal water and 152,500# 20-40 mesh sand.

Workover History: December 1985: Temporary packer set at 3500' to isolate casing failure.

January 1986: Fish temp packer, and squeeze casing leak between 965'

and 1581' with 100 sx cement.

February 1986: Install downhole pump and set pumping unit.

August 1986: Attempt to recover downhole pump. Pump stuck. Backoff rods above pump. Attempt to pull tubing. Pull 80,000# over and

attempt to rotate, no success. NU wellhead.

February 1994: Perforate tubing at 5922'-5949'. Swab well - recovered


some water. Tight spot in tubing from 3574' to 4270'.

Production History: 0.730 Bcf gas and 16.5 Mbbl oil.

SAN JUAN 32-9 UNIT # 4A

MESA VERDE

SE/4, Sec 12, T31N, R10W, San Juan Co, New Mexico



lwd 1/8/94