

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.

SF 078134

4. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT ACQUISITION NAME

8. FARM OR LEASE NAME

Crandell

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

Aztec Pic. Cliffs

11. SEC. T., R., M., OR S.E. AND
SURVEY OR AREA

Sec. 18, T-31-N, R-10-W

N.M., P.M.

12. COUNTY OR PARISH 13. STATE

San Juan

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

Southland Royalty Company

3. ADDRESS OF OPERATOR

Post Office Box 4289, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1690'S, 790'E

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, TO, OR, etc.)

5962'GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

POLE OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is intended to plug and abandon this well in the following manner:

2200' MOL&RU. TIH w/workstring and spot a 20 sx plug plug from TD (2780) to 2262' to cover the Pictured Cliffs and Fruitland. WOC and tag plug at 2262'. Spot a 10 sx plug from ~~1030-1220~~ to cover the Kirtland and Ojo Alamo formations. Perforate squeeze holes @ 292' (50' below the surface casing). Circulate cement down the 2 7/8" casing and back to surface in the 2 7/8 - 8 5/8" annular space (110 sx). Cut off wellhead and install a dry hole marker.

Rec.

JAN 05 1988

18. I hereby certify that the foregoing is true and correct

Drilling Clerk

12-28-87

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DEC 30 1987

DATE

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
CALLER SERVICE 4104
FARMINGTON, NEW MEXICO 87499

Attachement of Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: 7C Crandell

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. The Farmington Office, telephone (505) 325-4572, is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. The following modifications to your plugging program are to be made (when applicable):

* perf @ 1230' and place plug inside & outside 2 7/8" casing
from 1230' - 985'

Office Hours: 7:45 A.M. to 4:30 P.M.