



Garrey Carruthers
Governor

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

September 13, 1989

Steve McCament
Meridian Oil Inc.
P.O. Box 4289
Farmington, NM 87499

Re: Bradenhead Inspection Survey

Dear Mr. McCament:


312' 312' 10 w

An inspection was conducted on September 8, 1989 of the bradenheads on a number of Meridian's wells. Of those wells that were tested two appear to have problems; Lucerne A #6 and Lucerne A #1A. Gas was detected using an explosive meter in the soil around the wellhead on the Lucerne A #6 location and our records show that the cement was not circulated on the 2 7/8" (slim hole). In addition to the above there is dead vegetation surrounding the location. Gas was also detected in the soil around the wellhead on the Lucerne A #1A location and our records show that cement was not circulated on the intermediate.

You are directed to re-enter the referenced wells and perform remedial action immediately. You must notify this office before you commence.

If you have any questions beforehand, please contact me at 334-6178.

Yours truly,


Ernie Busch
Deputy Oil & Gas Inspector

EB/gb

cc: David Boyer
File