State of New Mexico Energy, Minerals and Natural Resources Department

	Oil Conservation	on Division	ℓ
	Sundry Notices and F	Reports on Well	s
			# (assigned by OCD) 30-045-23368
1. Type of Well GAS		5.	Lease Number
		6.	State Oil&Gas Lease # K-5737
2. Name of Operator SOUTHLAND ROYALTY COMPANY		7.	Lease Name/Unit Name Rattlesnake Canyon
3. Address & Phone No. of Operato		8.	Well No. 1A
PO Box 4289, Farmington, NM		9.	
4. Location of Well, Footage, Sec. 1045'FSL, 1175'FEL, Sec.32, T-		=	Elevation:
Type of Submission	Type of Act		
X Notice of Intent	Abandonment Recompletion	Change of Pl New Construc	ans tion
Subsequent Report	Casing Repair	Non-Routine Water Shut o	ff
Final Abandonment	Altering Casing _X_ Other -	Conversion t	o Injection
13. Describe Proposed or Comple	eted Operations		
It is intended to workover wellbore diagram.	the subject well accord	rding to the at	tached procedure and
		DE	<i>aemieo</i>

DECEIVED DEC 2 0 1994

OIL CON. DIV.

SIGNATURE July Mulfield (LWD6) Regulatory Affairs December 19, 1994

(This space for State Use)
Approved by Approved by Course OFFUTY OIL & GAS INSPECTOR, DIST. DEC 2 0 1994

WORKOVER PROCEDURE - PACKER REPAIR

RATTLESNAKE CANYON # 1A
Pictured Cliffs/Mesaverde Duel
SE/4 Sec. 32, T32N, R8W
San Juan Co., New Mexico

- 1. Comply to all NMOCD, BLM, and MOI regulations. Conduct daily safety meetings for all personnel on location.
- 2. Test location rig anchors and repair if necessary. Prepare blow pit. MOL and RU daylight pulling unit. Install a 400 bbl frac tank and an atmospheric blow tank. NU blooie line to blow pit, and relief line to atmospheric tank. Fill frac tank with fresh water.
- 3. Blow well down to atmospheric tank. Control well with fresh water as needed. ND wellhead and NU BOP's. Test and record operation of BOP's. Send wellhead to A-1 Machine for inspection and necessary re-dress.
- 4. PU on Pictured Cliffs tubing (3505' of 1 1/2", 2.76#), and strap out of hole. Control well with fresh water as needed. Visually inspect Pictured Cliffs tubing, and replace joints that are in bad condition. Note any buildup of scale and notify Operations Engineer.
- 5. PU on Mersverde tubing (5869' of 2 3/8" 4.7#), unseat PBR at 3610', and strap out of hole. Visually inspect Mesaverde tubing, and replace joints that are in bad condition. Note any buildup of scale and notify Operations Engineer.
- 6. Make casing scrapper (7", 20#) run with 2 3/8" tubing to top of liner at 6570'. PU 7" retrievable packer, TIH and set packer at 3400'. Pressure test 7" casing to 1000 psig, and POOH. If pressure test fails, contact Operations Engineer for repair procedure.
- 7. PU 3 7/8" bit and clean out to PBTD (6103') with air. Use string float as needed while blowing with air. Blow well clean and obtain gauges, and POOH.
- 8. TIH with Mesaverde tubing with seating nipple and pump out plug one joint off bottom, and PBR 2270' off bottom. Land tubing at 5880' with PBR seated at 3610'. Wireline set tubing choke one joint above PBR and pressure test Mesaverde tubing to 1500 psig.
- 9. TIH with Pictured Cliffs tubing, with seating nipple and blanking plug one joint off bottom, and land at 3500'.
- 10. ND BOP's and NU wellhead. Pull blanking plug from Pictured Cliffs tubing, and then pump plug from Mesaverde tubing.
- 11. Release rig, rerun packer integrity test, and re-establish production.

		Recommended	:			
		Operation		ns Engineer		
		Approval:				
			Drilling Superintendent			
Contacts: Downhole Tools Operations Engineer	Baker		325-0216			
	Operations Engineer	Larry D	illon	326-9714		

Rattlesnake Canyon #1A

CURRENT - 11-29-94

MV - PC Commingle

1045' FSL, 1175' FEL, Section 32, T-32-N, R-8-W, San Juan County, NM

Spud: 5-2-79

Completed: 7-8-79

Ojo Alamo @ 2170'

Kirtland @ 2225'

Fruitland @ 3070'

Lewis @ 3745'


Cliff House @ 5100'

Menefee @ 5490'

Point Lookout @5752'

Huerfanito Bentonite @ 4240'

Pictured Cliffs @ 3445'



PERTINENT DATA SHEET 12/12/94

WELLNAME:	Rattlesnake Ca	nyon #1A			DP NUMBER:		887 888	(MV) (PC)	
WELL TYPE:	Blanco Mesave Pictured Cliffs	rde	-		ELEVATION:	GL: KB:	65 47' 65 5 9'		
LOCATION:	Sec. 32, T32N,				INITIAL POTENTIAL:	AOF AOF	2,05 4 1,027		(MV) (PC)
	San Juan Cour	ity, New Mexi	co		SICP:		1,267	(PC)	
OWNERSHIP:	GWI: NRI:	(MV) 100.0000% 87.5000%	(PC) 100.0000% 87.5000%		DRILLING:	COM	D DATE: PLETED: DEPTH: PBTD:		05-02-79 0 7- 08-79 6105' 6103'
CASING RECORD:									
HOLE SIZE	SIZE	WEIGHT	GRADE	<u>DEPTH</u>	EQUIP.	CE	MENT	-	тос
12 1/4"	9 5/8"	36#	K55	232'	•	135 sx			Surfac
8 3/4"	7"	20#	K55	3735'		252 sx		TS	2100
6 1/4"	4 1/2"	10.5#	K55	3570' 6	105'	340 sx	F	Rev. 20 Bbl	3570
Tubing (MV) Tubing (PC)	2 3/8" 1 1/2"	4.7# 2.76#	CRS55 CRS55	5869' 350 5 '	PBR @ 3610	•			
FORMATION TOPS:	Ojo Alamo Kirtland Fruitland Pictured Cliffs Lewis Huerfanito Bei Cliff House	ntonite	2170' 2225' 3070' 3445' 3745' 4240' 5100'		Menefee Point Loc Dakota		5490' 5752'		
LOGGING:	GR-Induction,	GR-Density,	& GR-Correlat	tion Logs					
PERFORATIONS	(PC) (MV)	3446' 3502 5761' 5884							
STIMULATION:	(PC) (MV)		water & 99,00 water & 97,00						
WORKOVER HISTORY:	NONE		-						
PRODUCTION HISTORY:	Gas	<u>Oil</u>			DATE OF LAST PRODU	JCTION:	Gas	<u>Oil</u>	
Cumulative as of 1994: Current:	420.3 MMcf 1.4 MMcf/m	0 Bbl 0 Bbl	(MV) (MV)		Sep	tember, 1994	1.4 MMd	of 0 Bbl	(MV)
Cumulative as of 1994: Current:	0 Mcf 0 Mcf/m	0 Bbl 0 Bbl	(PC) (PC)						