Form 3160-5 (June 1990) DEPA BUREA	UNITED STATES RTMENT OF THE INTERIOR AU OF LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals		SF-078051 8. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Well Other 2. Name of Operator	Attention:	8. Well Name and No. Neal #2
Amoco Production Company	Gail M. Jefferson	9. API Well No.
3. Address and Telephone No.		3004523950
P.O. Box 800, Denver, Colorado 80201 (303) 830-6157		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Basin Dakota/Mesaverde
		11. County or Parish, State
830'FSL 1085FV	VL Sec. 4 T 31N R 11W Unit M	San Juan New Mexico
	PLATE BOW TO INDICATE NATURE OF NOTICE	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE , REPORT, OR OTHER DATA		NEFORT, ON OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION		
		Change of Plans
Notice of Intent	Abandonment	New Construction
	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
	Altering Casing Altering Casing Other Plug Dakot a/Recom. MV	Conversion to Injection
Final Abandonment Notice	(Note: Re	_] Dispose Water port results of multiple completion on Well Completion or
	Verrase of thes durin.	tion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give		
subsurface locations and measured and to Amoco Production Compan Mesaverde Horizon per the	rue vertical depths for all markers and zones pertinent to this work.)* by requests permission to plug the Dakota horizon and recomple attached procedures	ete the above referenced well to be
	uestions please contact Khanh Vu at (303) 830-4920 or myse	If at the number listed above for any
administrative questions.		
		·····
		DEARTH
		APR 2 0 1995 🗁
		OIL CON. DIT
		DUTT: 8
14.1 hereby certify that the oregoing is true a Signed	. Herson Title Sr. Admin. St	
/	V UU	
(This space for Federal or State office use)		
Approved by Title		APR 1.7 1995
Conditions of approval, if any:		A
		ANT IN INSTRICT MANAGER
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any fail of the States any fail of the United States any fail of the United States and the States and t		
* See Instructions on Reverse Side		

.

Neal 2 Orig. Comp. 07/80 TD = 7595', PBTD = 7570' Page 2 of 2

1st Version

- 1. Record TP, SICP, and SIBHP
- 2. MIRUSU
- 3. TIH with retainer and set at 7000'.
- 4. Plug DK by pumping 200 sacks of cement through the retainer. Cap retainer with 500' of cement to 6500'.
- 5. Pressure test casing to 3500 psi.
- 6. TIH with a 3 1/8" casing guns and perforate the following Point Lookout intervals with limited entry. Used Welex's GR/DL/IL log dated 5/9/80.

Point Lookout 5187-5283' 5468-5470'

- 8. Fracture stimulate according to the attached frac schedule for the Point Lookout.
- 9. Set RBP at 5150'.
- 10. Pressure test casing to 3500 psi.
- 11. TIH with a 3 1/8" casing guns and perforate the following Menefee intervals with limited entry. Used Welex's GR/DL/IL log dated 5/9/80.

Menefee 4775-4780' 4941-4949' 505-5056' 5101-5115'

- 8. Fracture stimulate according to the attached frac schedule for the Menefee.
- 9. Set RBP at 4760'.
- 10. Pressure test casing to 3500 psi.
- 11. TIH with a 3 1/8" casing guns and perforate the following Cliff House intervals with limited entry. Used Welex's GR/IL log dated 5/9/80.

Cliffhouse 4462-68' 4508-18' 4545-86' 4592-94' 4650-4745' 4762-66' 4772-86'

- 12. Fracture stimulate according to the attached frac schedule for the Cliff House.
- 13. TOH with RBP.
- 14. Reshoot MV intervals with 2 JSPF, 120 degree phasing, and 13 g.
- 15. Flow back Mesaverde until sand entry ceased.
- 16. Cleanout with N2.
- 17. TIH with 2 3/8" tubing and land at 5283' with a seating nipple one joint off bottom.
- 18. Continue to flow back load until well is capable of producing.
- 19. Tie the Mesaverde string back into surface equipment and turn over to production.

If problems are encountered, please contact:

Khanh Vu

W - (303) 830-4920 H - (303) 980-6324

