RECZIVED
FORM APPROVED Budget Bureau No. 1004-1111 Steppers Scoremoer to 1440
019 FARM SE-078039

			N.	-(VZU M	
	UNITED STA DEPARTMENT OF T UREAU OF LAND M	HE INTERIOR	91 Mga 25	FORM APPROVED Budget Bureau No. 11004-1115 Plan DELEMES Scoremoer 10. 1440 3 Lease Delegation and Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS				SF-078039	
Do not use this form for pro	posals to drill or to		different reservoir.	2 Withtild Rignee or Tribe Name	
SUBMIT IN TRIPLICATE				7. If Unit or C.A. Agreement Designation	
1. Type of Well Out Summer Coal Seam				8. Well Name and No.	
Well Well Coper Coal Seam 2. Name of Operator				Barnes Gas Com D #1	
Amoco Production Company Attn: John Hampton				9. API Well No.	
J. Address and Telephone No				30-045-27789	
P.O. Box 800, Denver, Colorado 80201				10 Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Basin Fruitland Coal	
1070' FEL x 990' FNL, NE/NE Sec. 24-32N-11W				11. County or Parish. State Gal	
				San Juan, New Mexico	
CHECK APPROPR	RIATE BOX(s) TO IN	IDICATE NATURE O	F NOTICE, REPOR	RT, OR OTHER DATA	
TYPE OF SUBMISSIO		TYPE OF ACTION			
Notice of Intent		Abandonment		Change of Plans	
, with or main		Recompletion		New Construction	
Sucrequent Report		Plugging Back	·	Non-Routine Fracturing	
	İ	Casing Reput		Water Shut-Off	
Final Abandonment Nou	ıce	Alternat Certail	1873	Conversion to Injection	
X Outer Whipstock				f multiple completion on Well Completion or	
			Recompletion Report at	nd Log form i	
13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally any give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work. 1°					
Amoco Production Company intends to whipstock the wellbore of the subject well using the					
attached procedures.					
				DECEINE	
				APR2 4 1991	
				OIL CON. DIV	
				OIL COIL. DIV	
Please call Cindy Burto	on at 303-830-51	19 if you have an	v questions.	DIST. 3	
				•	
(Verbal approval received from Wayne Journsend to Ju Manotti 3/21/91.)					
way a source to					
(be YVlanotti, 3/2/191.)					
ADDROVED					
,		m.	mriDIIIIT	U	
			IIUDIIIE		

14. I hereby certify thy the foresours in the and correct (Thus space of Federal or State office use)

Barnes Gas Com D No. 1

03/21/91

Window Cutting Procedure

PREPARATORY WORK

MIRUSU, pull tubing, set wireline RBP at 2600' RD Huberhead and weld on 11" 3000# casing head for 5 1/2" (Note: set at ground level). NU 7 1/16" tubing head. TIH with retrieving head and retrieve bridge plug. TIH with tubing and land at 2600', hang off. Modify location to accept the air drilling package (ie. change it to look like a "Top Set" location).

WINDOW CUTTING

- NU BOPS. (Note: Replace 3 1/2" DP rams with 2 7/8" rams.
- 2. TOH with 2 3/8" tubing and LD same.
- TIH with 5 1/2" A/Z packer/whipstock assembly and starting mill.
- 4. Set packer so that the top of the window will be at 2600' (isolating previous perforations). Casing collar at 2605' per HLS GR log run (07/05/90).
- 5. Shear carrier lug bolt with 40-75000# pull up.
- Commence cutting window with starting mill. Mill up lug bolt and TOH.
- 7. PU window cutting mill and watermelon mills, TIH cut window plus 3-5' of formation.
- 8. TOH x PU taper mill, string and watermelon mills.
- 9. TIH and elongate window and smooth out any burrs left in window. Mill 5'.
- 10. TOH and PU a building BHA/CST BHA:

```
4 3/4" Bladed mill
```

N.B. stabilizer

10 - 3 1/2" DC's with float

2 7/8" AOH drill pipe

11. Drill to TD with expected coals at:

2642-44 (of 2931) - TVD

2678-82

2715-20

2745-55

2811-32

2907-18

2926-31

Note: Have mud logger on location.

12. TOH and run CST procedure.

BARNES GAS COM /D/ #1 T32N R11W SEC 24 SW NE NE SAN JUAN COUNTY, NEW MEXICO

