

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-013642

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NA

7. UNIT AGREEMENT NAME

NA

8. FARM OR LEASE NAME

Gardner-C

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Basin Fruitland Coal

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA

25-32N-9W

12. COUNTY OR PARISH 13. STATE

SAN JUAN

NM

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Koch Exploration Company

3. ADDRESS OF OPERATOR

3605 N. DUSTIN Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface 1120' ENL-1820' FEH.

14. PERMIT NO.

15. ELEVATIONS (Show whether SF, RT, OR, etc.)

GR-6872

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

WELL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We have filed to drill this well through the coal and run & cement the pipe through the formation.

We want to change the plan as follows. Drill 200' of 11 3/4" hole.

Run 9 5/8" surface casing 200'. Cement with 92 sk. 100 cu. ft, 100% excess to circulate to surface. Drill 8 3/4" hole to top of coal zone. Run & cement 7" 20' casing at 3400' - with 1348 sks. 1680 cu. ft. cement. 100% excess to circulate to surface. Drill 6 1/4" hole through the coal zone (3400' - 3750

Complete open hole, then run a 5 1/2" 17' liner from 3350 to 3750
DO NO CEMENT.

RECEIVED

SEP 14 1990

18. I hereby certify that the foregoing is true and correct

SIGNED

William H. Pickett

TITLE

DIST. 3

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

8-29-90

SEP 07 1990

DATE

Ken Townsend

AREA MANAGER
FARMINGTON FIELD OFFICE

*See Instructions on Reverse Side