UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT			
Sundry Notices and Reports on	Wells	m., 1 = 6	
Sulidly Nooze	, FES - 0	Fil + 555.	Lease Number
			SF-081155
			If Indian, All. o
			Tribe Name
Type of Well GAS			Na
GAS	. •	7.	Unit Agreement Na
			Allison Unit
Name of Operator			
PUPI INGTQN	40		
BURLINGTON OIL & GAS COMPANY		, _₹ (;) 8 .	Well Name & Numb
			Allison Unit #52 API Well No. 30-045-29497 Field and Pool Blanco Mesaverdo
. Address & Phone No. of Operator	-9700	. 9.0	API WELL NO.
. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-	. 1		30-045-29497
PO BOX 1200)	(31.5)		Blanco Mesaverd
Location of Well, Footage, Sec., T, R, M	74.47 	ÇAKÎÎ.	. County and Stat
Location of Well, Footage, Sec., P. 650'FNL 2165'FWL, Sec.28, T-32-N, R-6-W, NMPM		11	San Juan Co, NM
030 1			San odan oo,
			DATA
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF	NOTICE,	REPORT, OTHE	K DAIR
2. CHECK APPROPRIATE BOX TO INDICATE TYPE	e of Act	ion	ດໄລກຮ
Time of Submission abandonment	t	_ (110.1.5)	- at i on
X Notice of Intent Recompletion	OI1	New Constru	e Fracturing
Subsequent Report Plugging B.	ack	_ Non-Routin	e fraccure
Subsequent Report — Plugging B. Casing Rep Altering C	air _	_ Water Shut	to Injection
Altering C	asing _	_ Conversion	to injus
Final Abandonment Altering C X_ Other -			
	3		
ar Completed Operations			
13. Describe Proposed or Completed Operations			
13. Describe Proposed or Completed Operations			rding to the
13. Describe Proposed or Completed Operations	he subje	ct well acco	rding to the
The is intended to repair the tubing on the	he subje	ct well acco	rding to the
13. Describe Proposed or Completed Operations It is intended to repair the tubing on the attached procedure.	he subje	ct well acco	rding to the
The is intended to repair the tubing on the	he subje	ct well acco	rding to the
The is intended to repair the tubing on the	he subje	ct well acco	rding to the
The is intended to repair the tubing on the	he subje	ct well acco	rding to the
The is intended to repair the tubing on the	he subje	ct well acco	rding to the
The is intended to repair the tubing on the	he subje	ct well acco	rding to the
The ic intended to repair the tubing on the	he subje	ct well acco	rding to the
The is intended to repair the tubing on the	he subje	ct well acco	rding to the
The is intended to repair the tubing on the	he subje	ct well acco	rding to the
The is intended to repair the tubing on the	he subje	ct well acco	rding to the
The is intended to repair the tubing on the	he subje	ct well acco	rding to the
It is intended to repair the tubing on the attached procedure.	he subje		rding to the
It is intended to repair the tubing on the attached procedure.	he subje		rding to the
It is intended to repair the tubing on the attached procedure.	he subje	i correct.	
It is intended to repair the tubing on the attached procedure.	he subje	i correct.	
It is intended to repair the tubing on the attached procedure. 14. I hereby certify that the foregoing is	he subje	i correct.	
It is intended to repair the tubing on the attached procedure. 14. I hereby certify that the foregoing is signed May Manhael MEL7) Title	true and	i correct. ory Administ	cator_Date 1/29/99 TLW
It is intended to repair the tubing on the attached procedure. 14. I hereby certify that the foregoing is signed Man Man MEL7) Title	true and	i correct. ory Administ	cator_Date 1/29/99 TLW
It is intended to repair the tubing on the attached procedure. 14. I hereby certify that the foregoing is signed Man Man MEL7) Title (This space for Federal or State Office use)	true and Requiat	d correct. ory Administr	cator_Date 1/29/99 TLW
It is intended to repair the tubing on the attached procedure. 14. I hereby certify that the foregoing is Signed Man Man MeLT?) Title	true and Regulat	i correct. Ory Administ:	cator Date 1/29/99 TLW

Allison Unit #52A

Mesaverde 650'FNL, 2165' FWL

Unit C, Section 28, T-32-N, R-6-W Latitude / Longitude: 36° 57.399' / 107° 27.891'

DPNO: 3571701 **Tubing Repair Procedure**

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Mesaverde, 2-3/8", 4.7# J-55 tubing is set at 6002'. Release donut, pick up additional joints of 3. tubing and tag bottom. (Record depth.) PBTD should be at +/- 6080'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- If fill, TIH with 3-7/8" bit, bit sub and watermelon mill on 2-3/8" tubing and round trip to below 4. perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
- 5. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.
- Land tubing at ±5880'. ND BOP and NU WH. Pump off expendable check. Connect to casing 6. and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended: M.E. Autur

Approved:

Bruce (). Boy 1. 26.99
Drilling Superintendent

Operations Engineer:

Mary Ellen Lutev

Office - (599-4052) Home - (325-9387)

Pager - (324-2671)